




**Haas**  
F1 Team  
OFFICIAL MACHINE TOOL

**HAAS FACTORY OUTLET**  
**A DIVISION OF PRODUCTIVITY INC**

# **HAAS MILL PROGRAMMING**



Revised 06/26 LL

**PROGRAMMING MANUAL**



This Manual is the Property of Productivity Inc

The document may not be reproduced without the express written permission of Productivity Inc, nor may it be sold. The content must not be altered, nor may the Productivity Inc name be removed from the materials.

This material is to be used as a guide to the operation of the machine tool. The Operator is responsible for following Safety Procedures as outlined by their instructor or manufacturer's specifications.

NOTE: Downloading and/or other use of this manual does not certify completion of the Training course. This manual is for reference only.

To obtain permission, please contact [trainingmn@productivity.com](mailto:trainingmn@productivity.com).

For more information on  
Additional Training Opportunities or our Classroom Schedules  
Contact the Productivity Inc Applications Department

Minneapolis: ☎ 763.476.8600

Cedar Rapids: ☎ 319.734.3403

Omaha: ☎ 402.330.2323

Denver: ☎ 800-947-8665

Salt Lake City: ☎ 801.886.2221

Visit us on the Web: [www.productivity.com](http://www.productivity.com)

### **HAAS Interactive Mill Operator Manual**

<https://www.haascnc.com/service/online-operator-s-manuals/mill-operator-s-manual/mill---introduction.html>

Note: Some of the content, images and screen shots included in this manual are taken from Haas manuals, controllers and web information with permission from Haas Automation Inc.  
2800 Sturgis Road Oxnard CA 93030-8933

## TABLE OF CONTENTS

|                                                                                           |    |
|-------------------------------------------------------------------------------------------|----|
| TOOL AND WORK OFFSETS .....                                                               | 6  |
| G54 WORK OFFSETS.....                                                                     | 6  |
| G43 TOOL LENGTH COMPENSATION + (ADD) / G44 TOOL LENGTH COMP - (SUBTRACT) (GROUP 08) ..... | 7  |
| G52 SET WORK COORDINATE SYSTEM (GROUP 00 OR 12).....                                      | 8  |
| G53 NON-MODAL MACHINE COORDINATE SELECTION (GROUP 00).....                                | 8  |
| G92 SET WORK COORDINATE SYSTEMS SHIFT VALUE (GROUP 00) .....                              | 8  |
| ABSOLUTE VS. INCREMENTAL POSITIONING (G90, G91).....                                      | 9  |
| Mill Incremental Positioning Example.....                                                 | 10 |
| Mill Absolute Positioning Example.....                                                    | 11 |
| Absolute and Incremental Exercise .....                                                   | 13 |
| CUTTING G-CODES .....                                                                     | 14 |
| Linear Interpolation Motion (G01) .....                                                   | 14 |
| Circular Interpolation Motion (G02/G03) .....                                             | 14 |
| G01 LINEAR INTERPOLATION MOTION (GROUP 01).....                                           | 15 |
| G02 CW / G03 CCW CIRCULAR INTERPOLATION MOTION (GROUP 01) .....                           | 17 |
| Using the R Address .....                                                                 | 17 |
| PROGRAMMING EXAMPLE .....                                                                 | 18 |
| THREAD MILLING.....                                                                       | 19 |
| THREAD MILLING EXAMPLE .....                                                              | 20 |
| OUTSIDE DIAMETER (O.D.) THREAD MILLING .....                                              | 21 |
| SINGLE-POINT THREAD MILLING.....                                                          | 22 |
| G02 / G03 EXAMPLES .....                                                                  | 23 |
| G01, G02 AND G03 MOTION .....                                                             | 24 |
| TOOL PATH EXERCISE 1.....                                                                 | 26 |
| TOOL PATH EXERCISE 2.....                                                                 | 27 |
| TOOL PATH EXERCISE 3.....                                                                 | 28 |
| TOOL PATH EXERCISE 4.....                                                                 | 29 |
| TOOL PATH EXERCISE 5.....                                                                 | 30 |
| TOOL PATH EXERCISE 6.....                                                                 | 31 |
| MILL PROGRAMMING.....                                                                     | 32 |
| BASIC PROGRAMMING .....                                                                   | 32 |
| PREPARATION.....                                                                          | 33 |
| CUTTING .....                                                                             | 34 |
| COMPLETION .....                                                                          | 34 |
| CUTTER COMPENSATION G41 / G42 .....                                                       | 35 |
| TOOL PATH WITHOUT CUTTER COMPENSATION – MANUAL COMPENSATION.....                          | 35 |

|                                                                                          |           |
|------------------------------------------------------------------------------------------|-----------|
| <b>CUTTER COMPENSATION .....</b>                                                         | <b>36</b> |
| <b>GENERAL DESCRIPTION OF CUTTER COMPENSATION.....</b>                                   | <b>36</b> |
| <b>FEED ADJUSTMENTS IN CUTTER COMPENSATION .....</b>                                     | <b>39</b> |
| Example of Tool Manufacture’s Technical Information .....                                | 43        |
| Cutter Compensation Exercise 1 .....                                                     | 44        |
| Cutter Compensation Exercise 2 .....                                                     | 45        |
| Cutter Compensation Exercise 3 .....                                                     | 46        |
| Cutter Compensation Exercise 4 .....                                                     | 47        |
| <b>G12 CIRCULAR POCKET MILLING CW / G13 CIRCULAR POCKET MILLING CCW (GROUP 00) .....</b> | <b>48</b> |
| Circular Pocket Milling, G12 Clockwise shown: [1] I only, [2] I, K and Q only.....       | 49        |
| Example G13 multiple-pass using I, K, Q, L, and G91:.....                                | 49        |
| G13 and G12 (Group 00) Exercise .....                                                    | 50        |
| <b>CANNED CYCLES.....</b>                                                                | <b>51</b> |
| <b>DRILLING CANNED CYCLES.....</b>                                                       | <b>51</b> |
| <b>TAPPING CANNED CYCLES.....</b>                                                        | <b>51</b> |
| <b>BORING AND REAMING CYCLES .....</b>                                                   | <b>52</b> |
| <b>R PLANES.....</b>                                                                     | <b>52</b> |
| <b>CANNED CYCLES G81 AND G82 .....</b>                                                   | <b>53</b> |
| <b>G81 DRILL CANNED CYCLE (GROUP 09) .....</b>                                           | <b>53</b> |
| <b>G82 SPOT DRILL CANNED CYCLE (GROUP 09) .....</b>                                      | <b>54</b> |
| G81 and G82 Canned Cycle Exercise.....                                                   | 56        |
| <b>G83 NORMAL PECK DRILLING CANNED CYCLE (GROUP 09) .....</b>                            | <b>58</b> |
| G83 Peck Drilling with I, J, K and Normal Peck Drilling: [#22] Setting 22.....           | 59        |
| <b>G83 AND G82 CANNED CYCLE EXERCISE .....</b>                                           | <b>60</b> |
| <b>G84 TAPPING CANNED CYCLE (GROUP 09).....</b>                                          | <b>61</b> |
| <b>G70 / G71 / G72 BOLT HOLE PATTERN .....</b>                                           | <b>63</b> |
| G70 Bolt Hole Circle (Group 00) .....                                                    | 64        |
| G71 Bolt Hole Arc (Group 00) .....                                                       | 64        |
| G72 Bolt Holes Along an Angle (Group 00).....                                            | 64        |
| <b>G81 CANNED CYCLE WITH G70 (BOLT HOLE CIRCLE) EXERCISE .....</b>                       | <b>66</b> |
| <b>G81 CANNED CYCLE WITH G70, G71 AND G72 EXERCISE .....</b>                             | <b>68</b> |
| <b>G73 HIGH-SPEED PECK DRILLING CANNED CYCLE (GROUP 09) .....</b>                        | <b>70</b> |
| <b>G98 CANNED CYCLE INITIAL POINT RETURN (GROUP 10).....</b>                             | <b>71</b> |
| <b>G99 CANNED CYCLE R PLANE RETURN (GROUP 10) .....</b>                                  | <b>71</b> |
| <b>FINAL EXERCISE (OPTIONAL) .....</b>                                                   | <b>72</b> |
| <b>G150 GENERAL PURPOSE POCKET MILLING (GROUP 00) .....</b>                              | <b>74</b> |
| G150 General Pocket Milling: [1] Start Point, [Z] Final depth.....                       | 74        |
| G150 General Purpose Pocket Milling: 0.500 diameter endmill.....                         | 75        |

|                                                                                                                        |    |
|------------------------------------------------------------------------------------------------------------------------|----|
| Absolute and Incremental examples of a subprogram called up by the <b>P####</b> command in the <b>G150</b> line: ..... | 75 |
| Square Island .....                                                                                                    | 75 |
| Round Island .....                                                                                                     | 76 |
| <b>SPECIAL G-CODES</b> .....                                                                                           | 77 |
| <b>ENGRAVING</b> .....                                                                                                 | 77 |
| <b>POCKET MILLING</b> .....                                                                                            | 77 |
| <b>ROTATION AND SCALING</b> .....                                                                                      | 77 |
| <b>MIRROR IMAGE</b> .....                                                                                              | 78 |
| <b>ROTATION AND SCALING</b> .....                                                                                      | 78 |
| <b>RIGID TAPPING</b> .....                                                                                             | 78 |
| <b>M19 SPINDLE ORIENTATION</b> .....                                                                                   | 78 |
| <b>HIGH-SPEED MACHINING</b> .....                                                                                      | 78 |
| <b>SUBPROGRAMS</b> .....                                                                                               | 79 |
| <b>SETTING UP SEARCH LOCATIONS</b> .....                                                                               | 79 |
| <b>LOCAL SUBPROGRAM (M97)</b> .....                                                                                    | 80 |
| <b>EXTERNAL SUBPROGRAM (M98)</b> .....                                                                                 | 80 |
| <b>THE MAIN PROGRAM (PROGRAM O40007) SPECIFIES (3) DIFFERENT CANNED CYCLES:</b> .....                                  | 81 |
| <b>MACROS INTRODUCTION</b> .....                                                                                       | 82 |
| <b>MILL G-CODES</b> .....                                                                                              | 83 |
| <b>MILL M-CODES</b> .....                                                                                              | 86 |
| <b>MILL SETTINGS INTRODUCTION</b> .....                                                                                | 88 |

## TOOL AND WORK OFFSETS

### G54 WORK OFFSETS

Work Offsets define where a work piece is located on the table.

Work Offsets available are **G54-G59**, **G110-G129**, and **G154 P1-P99**. **G110-G129** and **G154 P1-P20** refer to the same Work Offsets.

A practical method for increasing efficiency is to fixture multiple workpieces on the table and machine them within a single cycle. This is achieved by assigning each workpiece to its own Work Offset.

Refer to the G-code section of this manual for additional details. The following example demonstrates multi-part machining using an M97 local subprogram call during the cutting sequence.

```
%
O40005 (Work offsets ex-prog) ;
(G54 X0 Y0 is center left of part) ;
(Z0 is on top of the part) ;
(T1 is a drill) ;
(BEGIN PREPARATION BLOCKS) ;
T1 M06 (Select tool 1) ;
G00 G90 G40 G49 G54(Safe startup) ;
X0 Y0 ;
(Move to first work coordinate position-G54) ;
S1000 M03 (Spindle on CW) ;
G43 H01 Z0.1 (Tool offset 1 on) ;
M08 (Coolant on) ;
(BEGIN CUTTING BLOCKS) ;
M97 P1000 (Call local Subprogram) ;
G00 Z3. (Rapid retract) ;
G90 G110 G17 G40 G80 X0. Y0. ;

(Move to second work coordinate position-G110)
;
M97 P1000 (Call local Subprogram) ;
G00 Z3. (Rapid Retract) ;
G90 G154 P22 G17 G40 G80 X0. Y0. ;
(Move to third work coordinate position-G154
P22) ;
M97 P1000 (Call local Subprogram) ;
(BEGIN COMPLETION BLOCKS) ;
G00 Z0.1 M09 (Rapid retract, Coolant off) ;
G53 G49 Z0 M05 (Z home, Spindle off) ;
G53 Y0 (Y home) ;
M30 (End program) ;
N1000 (Local subprogram) ;
G81 F41.6 X1. Y2. Z-1.25 R0.1 (Begin G81) ;
(1st hole) ;
X2. Y2. (2nd hole) ;
G80 (Cancel G81) ;
M99 ;
%
```


## G43 TOOL LENGTH COMPENSATION + (ADD) / G44 TOOL LENGTH COMP - (SUBTRACT) (GROUP 08)

A G43 command applies positive tool length compensation by adding the tool length value from the offsets page to the commanded axis position. A G44 command applies negative tool length compensation by subtracting the tool length value. A non-zero H value must be specified to reference the correct tool offset entry.

**NOTE** Starting with NGC Software Version 100.21.000.1100, HAAS machines apply tool length offsets by default. The offset remains active unless explicitly canceled with G49/H00 on mills or a Txx00 offset on lathes. On mill machines, the tool length offset automatically updates after each tool change, and both the active tool length offset, and the associated Group 8 code persist through power cycles.

**CAUTION:** The tool length **nn** value must match the **nn** value specified in the **M06 Tnn** tool change command to prevent potential collisions.

**Setting 15 - H & T Code Agreement** controls whether the **nn** value needs to match in the **Tnn** and **Hnn** arguments. If Setting 15 is ON and the **Tnn** and **Hnn** do not match, Alarm 332 - H and T Not Matched is generated.



## G52 SET WORK COORDINATE SYSTEM (GROUP 00 OR 12)

G52 behaves differently depending on the value of Setting 33, which selects either Fanuc-style or Haas-style coordinates.

### Fanuc Mode (Setting 33 = FANUC)

G52 is a Group 00 G-code used to apply a global work coordinate shift. The values entered on the G52 line are added to all work offsets. These G52 values are automatically cleared at power-up, when reset is pressed, when changing modes, at the end of a program, or by issuing M30, G92, or G52 X0 Y0 Z0 A0 B0.

### Haas Mode (Setting 33 = HAAS)

G52 also functions as a global work coordinate shift, and the entered values are added to all work offsets. Unlike Fanuc mode, G52 values are cleared only by a G92 command. When G92 is used in Haas format, the current position in the active work coordinate system is shifted by the programmed X, Y, Z, A, and B values, and the G92 work offset reflects the difference between the current work offset and the commanded shift.

## G53 NON-MODAL MACHINE COORDINATE SELECTION (GROUP 00)

G53 temporarily cancels all work coordinate offsets and moves the machine using the machine coordinate system. It also **ignores any active tool length offsets**. In machine coordinates, the zero point for each axis corresponds to the position reached during a Zero Return. G53 applies only to the block in which it is commanded.

## G92 SET WORK COORDINATE SYSTEMS SHIFT VALUE (GROUP 00)

A G92 command cancels any active G52 shift for the specified axes. For example, **G92 X1.4** clears the G52 shift on the X-axis only.

The current G92 shift value appears at the bottom of the Work Offsets page and can be cleared from that display if needed. It is also cleared automatically at power-up and whenever **Zero Return → All** or **Zero Return → Single** is performed.

To clear a G92 shift within a program, issue another G92 command that returns the work offset to its original value.

## ABSOLUTE VS. INCREMENTAL POSITIONING (G90, G91)


Absolute (**G90**) and incremental (**G91**) positioning determine how the control interprets axis motion commands.

With **G90**, commanded positions are interpreted relative to the origin of the active coordinate system.

With **G91**, commanded positions are interpreted relative to the tool's current position.

Absolute programming is appropriate for most operations, while incremental programming is effective for repetitive, equally spaced movements.

Figure 1 illustrates a part with five equally spaced  $\varnothing 0.25$ " (13 mm) holes, each 1.00" (25.4 mm) deep and spaced 1.250" (31.75 mm) apart.



Absolute and incremental sample programs are shown below. **G54 X0. Y0.** is used for the incremental example [1], and **G54** is used for the absolute example [2].


The two programs demonstrate how to drill the holes shown in the drawing, allowing comparison between absolute and incremental positioning.

The holes are first started with a center drill, followed by drilling with a 0.250" (6.35 mm) drill bit. A depth cut of 0.200" (5.08 mm) is used for the center drill, and 1.00" (25.4 mm) for the 0.250" drill.

The **G81** drill canned cycle is used for all holes.

## MILL INCREMENTAL POSITIONING EXAMPLE

```
%  
O40002 (Incremental ex-prog) ;  
N1 (G54 X0 Y0 is center left of part) ;  
N2 (Z0 is on top of the part) ;  
N3 (T1 is a center drill) ;  
N4 (T2 is a drill) ;  
N5 (T1 PREPARATION BLOCKS) ;  
N6 T1 M06 (Select tool 1) ;  
N7 G00 G90 G40 G49 G54 (Safe startup) ;  
N8 X0 Y0 (Rapid to 1st position) ;  
N9 S1000 M03 (Spindle on CW) ;  
N10 G43 H01 Z0.1 (Tool offset 1 on) ;  
N11 M08 (Coolant on) ;  
N12 (T1 CUTTING BLOCKS) ;  
N13 G99 G91 G81 F8.15 X1.25 Z-0.3 L5 ;  
N14 (Begin G81, 5 times) ;  
N15 G80 (Cancel G81) ;  
N16 (T1 COMPLETION BLOCKS) ;  
N17 G00 G90 G53 Z0. M09 (rapid retract, clnt off) ;  
N18 M01 (Optional stop) ;  
N19 (T2 PREPARATION BLOCKS) ;  
N20 T2 M06 (Select tool 2) ;  
N21 G00 G90 G40 G49 (Safe startup) ;  
N22 G54 X0 Y0 (Rapid to 1st position) ;  
N23 S1000 M03 (Spindle on CW) ;  
N24 G43 H02 Z0.1 (Tool offset 2 on) ;  
N25 M08 (Coolant on) ;  
N26 (T2 CUTTING BLOCKS) ;  
N27 G99 G91 G81 F21.4 X1.25 Z-1.1 L5 ;  
N28 G80 (Cancel G81) ;  
N29 (T2 COMPLETION BLOCKS) ;  
N30 G00 Z0.1 M09 (Rapid retract, clnt off) ;  
N31 G53 G90 G49 Z0 M05 (Z home, spindle off) ;  
N32 G53 Y0 (Y home) ;  
N33 M30 (End program) ;  
%
```



---

## MILL ABSOLUTE POSITIONING EXAMPLE

The absolute program method requires more lines of code than the incremental method, although both use similar preparation and completion sections.

In the incremental example, the center-drill operation begins at line N13. The **G81** canned cycle uses the loop address **Lnn** to repeat the cycle a specified number of times. In this case, **L5** repeats the cycle five times. With each repetition, the machine moves the programmed X and Y increment—in this example, **1.25" in X**—from the current position before performing the drill cycle. The programmed drill depth is **0.1" deeper** than the actual depth to account for starting **0.1" above the part surface**.

In the absolute program, **G81** specifies the drill depth but does not use an L-code loop. Instead, each hole location is listed on a separate line, and the control performs the drill cycle at each position until **G80** cancels the canned cycle. The absolute method specifies the exact drill depth because motion begins at the part surface (**Z = 0**).

%

O40003 (Absolute ex-prog) ;

N1 (G54 X0 Y0 is center left of part) ;

N2 (Z0 is on top of the part) ;

N3 (T1 is a center drill) ;

N4 (T2 is a drill) ;

N5 (T1 PREPARATION BLOCKS) ;

N6 T1 M06 (Select tool 1) ;

N7 G00 G90 G40 G49 G54 (Safe startup) ;

N8 X1.25 Y0 (Rapid to 1st position) ;

N9 S1000 M03 (Spindle on CW) ;

N10 G43 H01 Z0.1 (Tool offset 1 on) ;

N11 M08 (Coolant on) ;

N12 (T1 CUTTING BLOCKS) ;

N13 G99 G81 F8.15 X1.25 Z-0.2 ;

N14 (Begin G81, 1st hole) ;

N15 X2.5 (2nd hole) ;

N16 X3.75 (3rd hole) ;

N17 X5. (4th hole) ;

N18 X6.25 (5th hole) ;

N19 G80 (Cancel G81) ;

N20 (T1 COMPLETION BLOCK) ;

N21 G00 G90 G53 Z0. M09 (Rapid retract, clnt off) ;

N22 M01 (Optional Stop) ;

N23 (T2 PREPARATION BLOCKS) ;

N24 T2 M06 (Select tool 2) ;

N25 G00 G90 G40 G49 (Safe startup) ;

N26 G54 X1.25 Y0 (Rapid to 1st position) ;

N27 S1000 M03 (Spindle on CW) ;

N28 G43 H02 Z0.1 (Tool offset 2 on) ;

N29 M08 (Coolant on) ;

N30 (T2 CUTTING BLOCKS) ;

N31 G99 G81 F21.4 X1.25 Z-1. (1st hole) ;

N32 X2.5 (2nd hole) ;

N33 X3.75 (3rd hole) ;

N34 X5. (4th hole) ;

N35 X6.25 (5th hole) ;

N36 G80 (Cancel G81) ;

N37 (T2 COMPLETION BLOCKS) ;


N38 G00 Z0.1 M09 (Rapid retract, Clnt off) ;

N39 G53 G49 Z0 M05 (Z home, Spindle off) ;


N40 G53 Y0 (Y home) ;

N41 M30 (End program) ;

%



## ABSOLUTE AND INCREMENTAL EXERCISE



Tool path example above starts from **Point 1** and ends on **Point 12**. **P1** through **P6** are in **ABSOLUTE (G90)** and **P6** through **P12** are **INCREMENTAL (G91)**.

| Absolute (G90) From X0 and Y0 |   |   | Incremental (G91) Starting from P6 |   |   |
|-------------------------------|---|---|------------------------------------|---|---|
|                               | X | Y |                                    | X | Y |
| P1                            |   |   | P7                                 |   |   |
| P2                            |   |   | P8                                 |   |   |
| P3                            |   |   | P9                                 |   |   |
| P4                            |   |   | P10                                |   |   |
| P5                            |   |   | P11                                |   |   |
| P6                            |   |   | P12                                |   |   |

## CUTTING G-CODES

The main cutting G-codes are categorized into interpolation motion and canned cycles. Interpolation motion cutting codes are broken down into:

**G01** - Linear Interpolation Motion

**G02** - Clockwise Circular Interpolation Motion

**G03** - Counter-Clockwise Circular Interpolation Motion

**G12** - Clockwise Circular Pocket Milling

**G13** - Counter-Clockwise Circular Pocket Milling

### Linear Interpolation Motion (G01)

**G01** is used to cut straight-line toolpaths. It requires a programmed feedrate (**F**). Optional axis words—**X**, **Y**, **Z**, and **A**—specify the target position. Once commanded, G01 remains active and continues to use the last programmed feedrate until another motion mode is selected, such as **G00**, **G02**, **G03**, **G12**, or **G13**.

Corners may be modified by using **C** for chamfers or **R** for corner rounding. Refer to *G01 Linear Interpolation Motion (Group 01)* for additional details.

---

### Circular Interpolation Motion (G02/G03)

**G02** (clockwise) and **G03** (counterclockwise) command circular cutting moves. Several optional address codes can be used to define the arc geometry. The motion begins at the tool's current position and moves along the programmed arc to the specified endpoint.

Arcs may be defined using either of two methods:

#### 1. I, J, K Method (Preferred)

- **I**, **J**, and **K** define the relative distances from the start point to the arc center.
- **X**, **Y**, and **Z** specify the absolute endpoint of the arc.
- This is the only method that allows programming of a full 360° circle; omitting the endpoint and specifying only I, J, or K produces a complete circle.

#### 2. R Method (Radius)

- The **R** value defines the radius from the start point to the center of the arc.
- The endpoint must still be defined with X, Y, or Z.
- Positive **R** values produce arcs  $\leq 180^\circ$ , while negative **R** values are used for arcs  $> 180^\circ$ .

## G01 LINEAR INTERPOLATION MOTION (GROUP 01)

**F** - Feedrate

\* **X** - X-Axis motion command

\* **Y** - Y-Axis motion command

\* **Z** - Z-Axis motion command

\* **A** - A-Axis motion command

\* **B** - B-Axis motion command

\* **C** - C-axis motion command

\* **,R** - Radius of the arc

\* **,C** - Chamfer distance

\*Indicates optional


**G01** moves the axes at a commanded feedrate and is primarily used for cutting. A **G01** move may involve a single axis or multiple axes simultaneously. The feedrate (**F**) can be specified in units per minute (**G94**), per spindle revolution (**G95**), or as inverse-time (**G93**). The control uses the most recently commanded **F** value until a new one is programmed; in **G93**, an **F** value must be specified on every line.

**G01** is a modal command and remains active until canceled by another motion mode such as **G00**, **G02**, or **G03**.

When **G01** is active, all programmed axes move and arrive at the endpoint simultaneously. If any axis cannot achieve the commanded feedrate, the machine will stop the move and generate a “maximum feedrate exceeded” alarm.

## Corner Rounding and Chamfering Example

### Corner Rounding and Chamfering Example #1



```
%  
O60011 (G01 CORNER ROUNDING & CHAMFER) ;  
(G54 X0 Y0 is at the top-right of part) ;  
(Z0 is on top of the part) ;  
(T1 is an end mill) ;  
(BEGIN PREPARATION BLOCKS) ;  
T1 M06 (Select tool 1) ;  
G00 G90 G40 G49 G54 (Safe startup) ;  
G00 G54 X0 Y0 (Rapid to 1st position) ;  
S1000 M03 (Spindle on CW) ;  
G43 H01 Z0.1 (Activate tool offset 1) ;  
M08 (Coolant on) ;  
(BEGIN CUTTING BLOCKS) ;  
G01 Z-0.5 F20. (Feed to cutting depth) ;  
Y-5. ,C1. (Chamfer) ;  
X-5. ,R1. (Corner-round) ;  
Y0 (Feed to Y0.) ;  
(BEGIN COMPLETION BLOCKS) ;  
G00 Z0.1 M09 (Rapid retract, Coolant off) ;  
G53 G49 Z0 M05 (Z home, Spindle off) ;  
G53 Y0 (Y home) ;  
M30 (End program) ;  
%
```

A chamfer or corner-rounding move can be automatically inserted between two linear interpolation blocks by adding **,C** (chamfer) or **,R** (corner rounding) to the beginning block. A terminating linear interpolation block must follow, although a **G04** dwell may appear between these blocks.

The two linear blocks define the intersection corner. When **,C** is used, the value specifies the distance from the intersection to both the start and end of the chamfer. When **,R** is used, the value specifies the radius of a circle tangent to the corner at the start and end of the rounding arc. Consecutive chamfer or corner-rounding blocks are permitted. These moves require motion in the two axes of the currently selected plane—XY (**G17**), XZ (**G18**), or YZ (**G19**).

## G02 CW / G03 CCW CIRCULAR INTERPOLATION MOTION (GROUP 01)

**F** - Feedrate

\* **I** - Distance along X Axis to center of circle

\* **J** - Distance along Y Axis to center of circle

\* **K** - Distance along Z Axis to center of circle

\* **R** - Radius of circle

\* **X** - X-Axis motion command

\* **Y** - Y-Axis motion command

\* **Z** - Z-Axis motion command

\* **A** - A-Axis motion command

\*Indicates optional



NOTE

**I, J** and **K** is the preferred method to program a radius. **R** is suitable for general radii.

These G-codes specify circular motion. Circular interpolation requires movement in two axes and must use the correct plane (**G17–G19**). There are two methods for programming a **G02** or **G03** move: using the **I, J, K** addresses or using the **R** address.

### Using I, J, K Addresses

**I, J**, and **K** define the distances from the starting point to the arc center. Only the addresses relevant to the selected plane are allowed—I/**J** for **G17**, **I/K** for **G18**, and **J/K** for **G19**. The **X, Y**, and **Z** commands specify the arc endpoint; if an axis endpoint is omitted, that axis remains at its starting value.

To cut a full circle, the **I, J, K** method must be used; an **R** value cannot produce a complete circle. A full circle is programmed by specifying only the **I/J/K** center values without an endpoint.

For example:

G02 I3.0 J4.0 (Assumes G17; XY plane)


### Using the R Address

The **R** value specifies the radius of the arc by defining the distance from the starting point to the center of the circle. A **positive R** value is used for arcs of **180° or less**, while a **negative R** value is used for arcs **greater than 180°**.

## PROGRAMMING EXAMPLE


### Positive R Address Programming Example

```
%  
O60021 (G02 POSITIVE R ADDRESS) ;  
(G54 X0 Y0 is at the bottom-left of part) ;  
(Z0 is on top of the part) ;  
(T1 is a .5 in dia endmill) ;  
(BEGIN PREPARATION BLOCKS) ;  
T1 M06 (Select tool 1) ;  
G00 G90 G40 G49 G54 (Safe startup) ;  
G00 G54 X-0.25 Y-0.25 (Rapid to 1st position) ;  
S1000 M03 (Spindle on CW) ;  
G43 H01 Z0.1 (Activate tool offset 1) ;  
M08 (Coolant on) ;  
(BEGIN CUTTING BLOCKS) ;  
G01 Z-0.5 F20. (Feed to cutting depth) ;  
G01 Y1.5 F12. (Feed to Y1.5) ;  
G02 X1.884 Y2.384 R1.25 (CW circular motion) ;  
(BEGIN COMPLETION BLOCKS) ;  
G00 Z0.1 M09 (Rapid retract, Coolant off) ;  
G53 Z0 M05 (Z home, Spindle off) ;  
G53 Y0 (Y home) ;  
M30 (End program) ;  
%
```



### Negative R Address Programming Example

```
%  
O60022 (G02 NEGATIVE R ADDRESS) ;  
(G54 X0 Y0 is at the bottom-left of part) ;  
(Z0 is on top of the part) ;  
(T1 is a .5 in dia endmill) ;  
(BEGIN PREPARATION BLOCKS) ;  
T1 M06 (Select tool 1) ;  
G00 G90 G40 G49 G54 (Safe startup) ;  
G00 G54 X-0.25 Y-0.25 (Rapid to 1st position) ;  
S1000 M03 (Spindle on CW) ;  
G43 H01 Z0.1 (Activate tool offset 1) ;  
M08 (Coolant on) ;  
(BEGIN CUTTING BLOCKS) ;  
G01 Z-0.5 F20. (Feed to cutting depth) ;  
G01 Y1.5 F12. (Feed to Y1.5) ;  
G02 X1.884 Y0.616 R-1.25 (CW circular motion) ;  
(BEGIN COMPLETION BLOCKS) ;  
G00 Z0.1 M09 (Rapid retract, Coolant off) ;  
G53 Z0 M05 (Z home, Spindle off) ;  
G53 Y0 (Y home) ;  
M30 (End program) ;  
%
```



## THREAD MILLING

Thread milling uses a standard **G02** or **G03** move to generate the circular motion in the X-Y plane, while simultaneously adding a Z-axis move on the same block to produce the thread pitch. This helical move generates one turn of the thread; the remaining threads are formed by the multiple teeth of the cutter. A typical example is:

```
N100 G02 I-1.0 Z-.05 F5. (Generates 1-inch radius for a 20-pitch thread)
```[1](L83)
```

### Thread Milling Notes

- Internal holes smaller than **3/8 inch** may not be practical.
- Always climb cut.
- Use **G03** for internal (I.D.) threads and **G02** for external (O.D.) threads.
- A right-hand I.D. thread moves **up** in Z by one pitch; a right-hand O.D. thread moves **down** in Z by one pitch.
- Pitch is calculated as:
  - o  $PITCH = 1 / TPI$  (e.g.,  $1 \div 8 TPI = 0.125$ ).[1](L85)

This example thread-mills a **1.5" diameter × 8 TPI** internal thread using a **0.750" diameter × 1.0"** thread hob. [1](L88)

### Thread Milling Steps

#### 1. Calculate the start position.

Subtract the cutter diameter from the hole diameter and divide by two:

$$(1.500 - 0.750) / 2 = 0.375$$

This value is the offset distance from the hole center to begin cutting.[1](L89)

#### 2. Turn on cutter compensation and move to the I.D.

After initial positioning, enable cutter compensation and position the cutter on the thread diameter.[1](L91)

#### 3. Program the helical move.

Execute a full circular move (**G02** or **G03**) while commanding a Z-axis move equal to one thread pitch. This creates the helical interpolation required for the thread form.

[1](L92)

#### 4. Exit the thread and cancel cutter compensation.

Move off the diameter using a linear move and then cancel compensation.[1](L93)

### Important Rule

Cutter compensation cannot be turned on or off during an arc move. A linear X or Y move must be programmed to transition onto or off the compensated diameter. This linear move defines the maximum allowable adjustment.[1](L94)


## THREAD MILLING EXAMPLE

Thread Milling Example, 1.5 Diameter X 8 TPI: [1]Tool Path, [2] Turn on and off cutter compensation.



### NOTE

Many thread mill manufacturers offer free online software to help you create your threading programs.



```
%
O60023 (G03 THREAD MILL 1.5-8 UNC) ;
(G54 X0 Y0 is at the center of the bore) ;
(Z0 is on top of the part) ;
(T1 is a .5 in dia thread mill) ;
(BEGIN PREPARATION BLOCKS) ;
T1 M06 (Select tool 1) ;
G00 G90 G40 G49 G54 (Safe startup) ;
G00 G54 X0 Y0 (Rapid to 1st position) ;
S1000 M03 (Spindle on CW) ;
G43 H01 Z0.1 (Activate tool offset 1) ;
M08 (Coolant on) ;
(BEGIN CUTTING BLOCKS) ;
G01 Z-0.5156 F50. (Feed to starting depth) ;
(Z-0.5 minus 1/8th of the pitch = Z-0.5156) ;
G41 X0.25 Y-0.25 F10. D01 (cutter comp on) ;
G03 X0.5 Y0 I0 J0.25 Z-0.5 (Arc into thread) ;
(Ramps up by 1/8th of the pitch) ;
I-0.5 J0 Z-0.375 F20. (Cuts full thread) ;
(Z moving up by the pitch value to Z-0.375) ;
X0.25 Y0.25 I-0.25 J0 Z-0.3594 (Arc out of thread) ;
(Ramp up by 1/8th of the pitch) ;
G40 G01 X0 Y1 (cutter comp off) ;
(BEGIN COMPLETION BLOCKS) ;
G00 Z0.1 M09 (Rapid retract, Coolant off) ;
G53 Z0 M05 (Z home, Spindle off) ;
G53 Y0 (Y home) ;
M30 (End program) ;
%
```

### Specific line description:

N5 = XY at the center of the hole

N7 = Thread depth, minus 1/8 pitch

N8 = Enable Cutter Compensation

N9 = Arcs into thread, ramps up by 1/8 pitch

N10 = Cuts full thread, Z moving up by the pitch value

N11 = Arcs out of thread, ramps up 1/8 pitch

N12 = Cancel Cutter Compensation




### NOTE

Maximum cutter compensation adjustability is 0.175.

## OUTSIDE DIAMETER (O.D.) THREAD MILLING

O.D. Thread Milling Example, 2.0 diameter post x 16 TPI: [1] Tool Path [2] Rapid Positioning, Turn on and off cutter compensation, [3] Start Position, [4] Arc with Z.

```
%  
O60024 (G02 G03 THREAD MILL 2.0-16 UNC) ;  
(G54 X0 Y0 is at the center of the post) ;  
(Z0 is on top of the post) ;  
(T1 is a .5 in dia thread mill) ;  
(BEGIN PREPARATION BLOCKS) ;  
T1 M06 (Select tool 1) ;  
G00 G90 G40 G49 G54 (Safe startup) ;  
G00 G54 X0 Y2.4 (Rapid to 1st position) ;  
S1000 M03 (Spindle on CW) ;  
G43 H01 Z0.1 (Activate tool offset 1) ;  
M08 (Coolant on) ;  
(BEGIN CUTTING BLOCKS) ;  
G00 Z-1. (Rapids to Z-1.) ;  
G01 G41 D01 X-0.5 Y1.4 F20. (Linear move) ;  
(Cutter comp on) ;  
G03 X0 Y0.962 R0.5 F25. (Arc into thread) ;  
G02 J-0.962 Z-1.0625 (Cut threads while lowering Z) ;  
G03 X0.5 Y1.4 R0.5 (Arc out of thread) ;  
G01 G40 X0 Y2.4 F20. (Linear move) ;  
(Cutter comp off) ;  
(BEGIN COMPLETION BLOCKS) ;  
G00 Z0.1 M09 (Rapid retract, Coolant off) ;  
G53 Z0 M05 (Z home, Spindle off) ;  
G53 Y0 (Y home) ;  
M30 (End program) ;  
%
```



**NOTE** A cutter compensation move can consist of any X or Y move from any position as long as the move is greater than the amount being compensated.

## SINGLE-POINT THREAD MILLING

This program thread-mills a 1.0" diameter hole using a 0.500" cutter and a 0.125" (8 TPI) thread pitch. It begins in absolute positioning (**G90**) and switches to incremental positioning (**G91**) at line **N7**.

The use of an *Lxx* value on line *N10* allows us to repeat the thread milling arc multiple times, with a Single-Point Thread Mill.


|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <pre>% O60025 (G03 SNGL PNT THREAD MILL 1.5-8 UNC) ; (G54 X0 Y0 is at the center of the bore) ; (Z0 is on top of the part) ; (T1 is a .5 in dia thread mill) ; (BEGIN PREPARATION BLOCKS) ; T1 M06 (Select tool 1) ; G00 G90 G40 G49 G54 (Safe startup) ; G00 G54 X0 Y0 (Rapid to 1st position) ; S1000 M03 (Spindle on CW) ; G43 H01 Z0.1 (Activate tool offset 1) ; M08 (Coolant on) ; (BEGIN CUTTING BLOCKS) ; G91 G01 Z-0.5156 F50. (Feed to starting depth) ; (Z-0.5 minus 1/8th of the pitch = Z-0.5156) ; G41 X0.25 Y-0.25 F20. D01 (Cutter comp on) ; G03 X0.25 Y0.25 I0 J0.25 Z0.0156 (Arc into thread) ; (Ramps up by 1/8th of the pitch) ; I-0.5 J0 Z0.125 L5 (Thread cut, repeat 5 times) ; X-0.25 Y0.25 I-0.25 J0 Z0.0156 (Arc out of thread) ; (Ramps up by 1/8th of the pitch) ; G40 G01 X-0.25 Y-0.25 (Cutter comp off) ; (BEGIN COMPLETION BLOCKS) ; G00 Z0.1 M09 (Rapid retract, Coolant off) ; G53 Z0 M05 (Z home, Spindle off) ; G53 Y0 (Y home) ; M30 (End program) ; %</pre> | <p><b>Specific line description:</b></p> <p><i>N5</i> = XY at the center of the hole</p> <p><i>N7</i> = Thread depth, minus 1/8 pitch. Switches to G91</p> <p><i>N8</i> = Enable Cutter Compensation</p> <p><i>N9</i> = Arcs into thread, ramps up by 1/8 pitch</p> <p><i>N10</i> = Cuts full thread, Z moving up by the pitch value</p> <p><i>N11</i> = Arcs out of thread, ramps up 1/8 pitch</p> <p><i>N12</i> = Cancel Cutter Compensation</p> <p><i>N13</i> = Switches back to G90 Absolute positioning</p> |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|

### Helical Motion

Helical (spiral) motion is possible with *G02* or *G03* by programming the linear axis that is not in the selected plane. This third axis will be moved along the specified axis in a linear manner, while the other two axes will be moved in the circular motion. The speed of each axis will be controlled so that the helical rate matches the programmed feedrate.

## G02 / G03 EXAMPLES

Below are examples demonstrating the two methods for programming a 2" (or 2 mm) radius, 180-degree counterclockwise arc. The tool begins at **X0 Y0** [1], moves to the arc's starting point [2], and then cuts the arc to the endpoint [3].



### Method 1:

```
%
T01 M06 ;
G00 X4. Y2. ;
G01 F20.0 Z-0.1 ;
G03 F20.0 I-2.0 J0. X0. Y2. ;
M30 ;
%
```


### Method 2:

```
%
T01 M06 ;
...
G00 X4. Y2. ;
G01 F20.0 Z-0.1 ;
G03 F20.0 X0. Y2. R2. ;
M30 ;
%
```

Below is an example of how to cut a 2" (or 2 mm) **radius circle**:

```
%
T01 M06 ;
G00 X4. Y2. ;
G01 F20.0 Z-0.1 ;
G02 F20.0 I2.0 J0. ;
M30 ;
%
```

## G01, G02 AND G03 MOTION




All Feed moves below have the same start position, **X1.0 Y1.0**, and the same end position, **X3.0 Y2.0**.

| Line 1                                                          | Line 2                                                               | Line 3                                                               |
|-----------------------------------------------------------------|----------------------------------------------------------------------|----------------------------------------------------------------------|
| G00 <b>X1.0 Y1.0</b><br><b>G01</b> <b>X3.0 Y2.0</b> F20.<br>M30 | G00 <b>X1.0 Y1.0</b><br><b>G02</b> <b>X3.0 Y2.0</b> R3.0 F20.<br>M30 | G00 <b>X1.0 Y1.0</b><br><b>G03</b> <b>X3.0 Y2.0</b> R1.5 F20.<br>M30 |

[illegible]

## TOOL PATH EXERCISE 1




**All exercises in this manual use climb milling. Program all toolpaths clockwise around the outside of the part profile.**

**HAAS Simulator: Go to MDI Mode:**

```
T1 M06  
G54 G90  
G00 X0. Y0.  
G01 X__ Y__ F20.0 →  
...  
...  
...  
...  
...  
...  
M30
```

**Run program in Graphic Mode.  
Save program referencing page number.**

## TOOL PATH EXERCISE 2



**Use G90, Absolute with G02 and G03**


**HAAS Simulator: Go to MDI Mode:**

```
T1 M06
G54 G90
G00 X0. Y0.
G01 X__ Y__ F20.0 →
...
...
...
...
...
...
M30
```

**Run program in Graphic Mode.**

**Save program referencing page number.**

### TOOL PATH EXERCISE 3




**Use G02 and G03 with I and J ONLY**

**HAAS Simulator: Go to MDI Mode:**

```
T1 M06
G54 G90
G00 X0. Y0.
G01 F20.0 .... →
...
...
...
...
...
...
...
M30
```

**Run program in Graphic Mode.**  
**Save program referencing page number.**


**Example for 1<sup>st</sup> Radius tool path:**



**Distance shifted in I or J Determines the size of the Arc / Circle**

**G02 X0.5 Y2.0 I0.5 ; (Arc Center Shifted 0.5" along X + )**

## TOOL PATH EXERCISE 4




**Use only G01 with ,R#.#**

**HAAS Simulator: Go to MDI Mode:**

**Example for 1<sup>st</sup> Radius tool path:**

```
T1 M06
G54 G90
G00 X0. Y0.
G01 F20.0 .... →
...
...
...
...
...
...
...
M30
```




**0.5" radius at the end of linear move**

```
G01 Y2.0 ,R0.5 ;
X2.0 ;
```

**Run program in Graphic Mode.  
Save program referencing page number.**

## TOOL PATH EXERCISE 5



### Use G91, Incremental with G01, R#.#, G02 or G03

## HAAS Simulator: Go to MDI Mode:

T1 M06

G54 G90

**G00 X0. Y0. (Must rapid to Absolute starting origin)**

**G91**

G01 F20.0 ... →

...

...

...

...


...

M30

**Run program in Graphic Mode.**

**Save program referencing page number.**

## TOOL PATH EXERCISE 6



**Program Tool Path Using any Method. G01 w/ ,R#.#, G02, or G03. Incremental or Absolute.**

**HAAS Simulator: Go to MDI Mode:**

```
T1 M06
G54 G90
G00 X0. Y0.
G01 F20.0 .... →
...
...
...
...
M30
```

**Run program in Graphic Mode.**

**Save program referencing page number.**

# MILL PROGRAMMING

## BASIC PROGRAMMING

A typical CNC program has (3) parts:

**Preparation:** Defines the work and tool offsets, loads the required cutting tool, sets spindle speed, enables coolant, and selects absolute or incremental positioning for axis motion.

**Cutting:** Specifies the toolpath and feedrate for the machining operation.

**Completion:** Retracts the spindle, turns off the spindle and coolant, and moves the table to a safe location for part unloading and inspection.

This basic program makes a 0.100" (2.54 mm) deep cut with Tool 1 along a straight-line path from X = 0.0, Y = 0.0 to X = -4.0, Y = -4.0.

**NOTE:** A program block may contain multiple G-codes, provided they belong to different groups. Two G-codes from the same group cannot appear in the same block. Only one M-code is permitted per block.

```
%  
O40001 (Basic program) ;  
(G54 X0 Y0 is top right corner of part) ;  
(Z0 is on top of the part) ;  
(T1 is a 1/2" end mill) ;  
(BEGIN PREPARATION BLOCKS) ;  
G00 G90 G17 G40 G49 G54 (Safe startup) ;  
T1 M06 (Select tool 1) ;  
G43 H01 (Tool offset 1 on) ;  
X0 Y0 (Rapid to 1st position) ;  
Z2.0 (Rapid to 2.0 Inch Above the part)  
S1000 M03 (Spindle on CW) ;  
M08 (Coolant on) ;  
(BEGIN CUTTING BLOCKS) ;  
G01 F20. Z-0.1 (Feed to cutting depth) ;  
X-4. Y-4. (linear motion) ;  
(BEGIN COMPLETION BLOCKS) ;  
G00 Z0.1 M09 (Rapid retract, Coolant off) ;  
G53 Z0 M05 (Z home, Spindle off) ;  
G53 Y0 (Y home) ;  
M30 (End program) ;  
%
```

**\*\*\*See Sample Program on USB Drive;  
O40001.NC**

## PREPARATION

These are the preparation code blocks in the sample program **O40001**:

| Preparation Code Block                           | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
|--------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>%</b>                                         | Denotes the beginning of a program.                                                                                                                                                                                                                                                                                                                                                                                                                         |
| <b>O40001 (Basic program) ;</b>                  | O40001 is the program name. Program names follow the Onnnnn format, where the letter “O” is followed by a five-digit number.                                                                                                                                                                                                                                                                                                                                |
| <b>(G54 X0 Y0 is top right corner of part) ;</b> | Comment                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| <b>(Z0 is on top of the part) ;</b>              | Comment                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| <b>(T1 is a 1/2" end mill) ;</b>                 | Comment                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| <b>(BEGIN PREPARATION BLOCKS) ;</b>              | Comment                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| <b>G00 G90 G17 G40 G49 G54 (Safe startup) ;</b>  | <p>This line is referred to as a <b>safe startup block</b>, and it is good machining practice to include it after every tool change. <b>G00</b> sets subsequent axis motion to rapid mode.</p> <p><b>G90</b> selects absolute positioning. <b>G17</b> selects the XY cutting plane, <b>G40</b> cancels cutter compensation, <b>G49</b> cancels tool length compensation, and <b>G54</b> activates the work coordinate system defined in the G54 offset.</p> |
| <b>T1 M06 (Select tool 1)</b>                    | Selects tool T1 to be used. M06 commands the tool changer to load Tool 1 (T1) into the spindle.                                                                                                                                                                                                                                                                                                                                                             |
| <b>G43 H01 (Tool offset 1 on)</b>                | <b>G43 H01</b> activates positive tool length compensation. The <b>H01</b> value instructs the control to apply the tool length stored for Tool 1 in the Tool Offset table. <b>NOTE:</b> Z Axis will move to position if there's any Z Axis command.                                                                                                                                                                                                        |
| <b>X0 Y0 (Rapid to 1st position)</b>             | X0 Y0 commands the table to move to X = 0.0 and Y = 0.0 using Work Offset <b>G54</b> .                                                                                                                                                                                                                                                                                                                                                                      |
| <b>Z2.0</b>                                      | Rapid Z Axis to 2.0" above the part using both <b>Tool and Work Offset combined</b> .                                                                                                                                                                                                                                                                                                                                                                       |
| <b>S1000 M03 (Spindle on CW)</b>                 | <p><b>M03</b> turns the spindle on in a clockwise direction. The <b>Snnnn</b> address specifies the desired spindle RPM.</p> <p>On machines equipped with a gearbox, the control automatically selects high or low gear based on the commanded spindle speed. <b>M41</b> and <b>M42</b> may be used to override this behavior when needed.</p>                                                                                                              |
| <b>M08 (Coolant on)</b>                          | M08 turns the coolant on.                                                                                                                                                                                                                                                                                                                                                                                                                                   |

## CUTTING

These are the cutting code blocks in the sample program O40001:


| Cutting Code Block                              | Description                                                                                                                                       |
|-------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>G01 F20. Z-0.1 (Feed to cutting depth) ;</b> | <b>G01 F20.</b> sets linear interpolation at a feedrate of 20" (508 mm) per minute. <b>Z-0.1</b> commands the Z-axis to move to <b>Z = -0.1</b> . |
| <b>X-4. Y-4. (linear motion) ;</b>              | X-4. Y-4. commands the X-axis to move to X = -4.0 and the Y-axis to move to Y = -4.0.                                                             |

## COMPLETION

| Completion Code Block                              | Description                                                                                                                                                                                                                          |
|----------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>G00 Z0.1 M09 (Rapid retract, Coolant off) ;</b> | <b>G00</b> commands rapid-motion positioning, <b>Z0.1</b> moves the Z-axis to <b>Z = 0.1</b> , and <b>M09</b> turns the coolant off.                                                                                                 |
| <b>G53 Z0 M05 (Z home, Spindle off) ;</b>          | <b>G53</b> commands the subsequent axis motion to be executed in the machine coordinate system. The <b>Z0</b> command moves the <b>Z-axis</b> to the machine home position at <b>Z = 0.0</b> , and <b>M05</b> turns the spindle off. |
| <b>G53 Y0 (Y home) ;</b>                           | <b>G53</b> commands the subsequent axis motion to be executed in the machine coordinate system. The <b>Y0</b> command moves the <b>Y-axis</b> to the machine home position at <b>Y = 0.0</b> .                                       |
| <b>M30 (End program) ;</b>                         | <b>M30</b> ends the program and moves the cursor on the control to the top of the program.                                                                                                                                           |
| <b>%</b>                                           | Denotes the end of a program.                                                                                                                                                                                                        |

## CUTTER COMPENSATION G41 / G42

### TOOL PATH WITHOUT CUTTER COMPENSATION – MANUAL COMPENSATION



The Tool Path above requires additional calculation for **0.75"** Diameter Tool.

Y Axis requires an additional **+0.217"** movement to clear the first **120** Degree angle.

Y Axis requires **+0.066"** and X Axis requires **+0.114"** to clear second **150** Degree angle.

## CUTTER COMPENSATION

Cutter compensation offsets the toolpath so the tool centerline runs to the left or right of the programmed path, allowing the control to adjust feature size using the wear values entered on the offsets page.

The offset may be specified as either a **Diameter** or a **Radius**, depending on **Setting 40**. In diameter mode, the control applies half of the entered value as the actual offset. Total compensation is the sum of the geometry and wear values.

Cutter compensation is available in X and Y for 2D machining (G17), and in X, Y, and Z for 3D machining with G141.

## GENERAL DESCRIPTION OF CUTTER COMPENSATION

**G41 (Climb Milling)** selects cutter compensation left, shifting the tool to the left of the programmed path.

**G42 (Conventional Milling)** selects cutter compensation right, shifting the tool to the right of the programmed path.

A G41 or G42 command must include a **Dnnn** value to select the correct offset from the tool offset table. The D-number corresponds to the entry in the far-left column, and the control applies the value found in the GEOMETRY column—either **D** (diameter mode) or **R** (radius mode), depending on **Setting 40**.

If a negative value is entered for the offset, cutter compensation behaves as though the opposite G-code were commanded. For example, a negative value used with G41 will act like a positive value used with G42. When cutter compensation is active, circular motions are allowed only in the **X-Y plane (G17)**; cutter compensation is limited to 2D motion in that plane.

**G40** cancels cutter compensation and is the default state at power-on. When cutter compensation is not active, the tool centerline follows the programmed path. A program cannot end (M30, M00, M01, or M02) with cutter compensation active.

The control evaluates cutter compensation one block at a time but looks ahead to the next two blocks containing X or Y motion to check for interference. **Setting 58** determines how this behavior is applied, with available options **Fanuc** or **YASNAC**.


If **Setting 58** is set to **YASNAC**, the control must be able to place the side of the tool along the programmed contour without overcutting the following two motions. In this mode, a circular motion is inserted to connect all outside angles.

When **Setting 58** is configured to *Fanuc*, the control does not require the tool's cutting edge to remain in contact with all segments of the programmed contour, reducing the likelihood of overcutting. However, if the programmed path would cause an overcut, the control will stop and issue an alarm. For outside angles of 270° or less, the control produces a sharp corner; for angles greater than 270°, it automatically inserts an additional linear move.

The diagrams illustrate how cutter compensation behaves under the different Setting 58 modes. Notably, a short linear move—smaller than the tool radius and perpendicular to the previous motion—is permitted only when using the Fanuc option.


**Cutter Compensation,  
YASNAC Style, G41 with a  
Positive Tool Diameter or G42  
with a Negative Tool  
Diameter:**

[1] Tool Path Actual Center,  
[2] Programmed Tool Path,  
[3] Start Point,  
[4] Cutter Compensation. G41  
/ G42 and G40 are  
commanded at the start and  
end of the tool path.




**Cutter Compensation,  
YASNAC Style, G42 with a  
Positive Tool Diameter or G41  
with a Negative Tool  
Diameter:**

[1] Tool Path Actual Center,  
[2] Programmed Tool Path,  
[3] Start Point,  
[4] Cutter Compensation. G41  
/ G42 and G40 are  
commanded at the start and  
end of the tool path.




**Cutter Compensation, FANUC Style, G41 with a Positive Tool Diameter or G42 with a Negative Tool Diameter:**

[1] Tool Path Actual Center,  
[2] Programmed Tool Path,  
[3] Start Point,  
[4] Cutter Compensation. G41 / G42 and G40 are commanded at the start and end of the tool path.



**Cutter Compensation, FANUC Style, G42 with a Positive Tool Diameter or G41 with a Negative Tool Diameter:**


[1] Tool Path Actual Center,  
[2] Programmed Tool Path,  
[3] Start Point,  
[4] Cutter Compensation. G41 / G42 and G40 are commanded at the start and end of the tool path.



### Improper Cutter Compensation:

[1] Move is less than cutting comp radius,  
[2] Workpiece,  
[3] Tool.

**NOTE:** A small cut of less than tool radius and at a right angle to the previous motion will only work with the Fanuc setting. A cutter compensation alarm will be generated if the machine is set to the YASNAC setting.



## FEED ADJUSTMENTS IN CUTTER COMPENSATION


When cutter compensation is active during circular interpolation, the control may adjust the programmed feedrate. For inside arcs, the feedrate is reduced to prevent surface speed from exceeding the intended cutting conditions. Excessive reduction can impact performance, so Setting 44 limits the allowable slowdown from 1% to 100%. At 100%, no feed reduction is applied; at 1%, the feedrate may be reduced to as little as 1% of the programmed value.

For outside arcs, the control does not increase the feedrate—no speed-up adjustment is applied.




### Cutter Compensation Entry (YASNAC) Type A and B:

[1] Programmed Path,  
[2] Tool Center Path,  
[r] Tool Radius

TYPE A




TYPE B






## Cutter Compensation Entry (Fanuc style) Type A and B:

[1] Programmed Path,  
[2] Tool Center Path,  
[r] Tool Radius

TYPE A



TYPE B



## Circular Interpolation and Cutter Compensation

This section describes the use of **G02** (clockwise circular interpolation), **G03** (counterclockwise circular interpolation), and cutter compensation (**G41** left, **G42** right).

Using **G02** and **G03**, the machine can cut circular moves and radii. For most profiles or contours, the simplest way to program a radius between two points is by using an **R** value. For full 360° circular moves, an **I** or **J** value must be specified. The accompanying circle-section illustration identifies the various arc segments.


Cutter compensation allows the programmer to shift the toolpath by an exact amount so the machine can cut profiles or contours to the print's true dimensions. By using cutter compensation, real dimensions can be programmed directly, reducing calculation time and the risk of programming errors while providing precise control of part size and geometry.

Here are several important rules you must follow for successful cutter compensation. Always refer to these guidelines when writing programs.

1. **Turn cutter compensation ON with a G01 X,Y move that is equal to or greater than the cutter radius (or the compensation amount).**
2. **When the operation is complete, turn cutter compensation OFF using the same method required to turn it on.** The entry and exit moves must follow the same rules—what is put in must be taken out.
3. **On most machines, a linear X,Y move smaller than the cutter radius may not work while compensation is active.** Set **Setting 58 to Fanuc** for best results in these cases.
4. **Cutter compensation cannot be turned ON or OFF during a G02 or G03 arc move.**
5. **With cutter compensation active, machining an inside arc with a radius smaller than the active D-value will generate an alarm.** A tool that is too large cannot cut an inside radius that is too small.


This illustration shows how the toolpath is calculated when cutter compensation is applied.

The detail view displays the tool in its starting position and then in the offset position as it engages the workpiece.



## Circular Interpolation G02 and G03:

- [1] 0.250" diameter endmill,
- [2] Programmed path,
- [3] Center of Tool,
- [4] Start Position,
- [5] Offset Tool Path.



## Programming exercise showing tool path.

This program uses cutter compensation. The toolpath is programmed to the centerline of the cutter. This is also the way the control calculates for cutter compensation.

```
%
O40006 (Cutter comp ex-prog) ;
(G54 X0 Y0 is at the lower left of part corner) ;
(Z0 is on top of the part) ;
(T1 is a .250 dia endmill) ;
(BEGIN PREPARATION BLOCKS) ;
T1 M06 (Select tool 1) ;
G00 G90 G40 G49 G54 (Safe startup) ;
X-1. Y-1. (Rapid to 1st position) ;
S1000 M03 (Spindle on CW) ;
G43 H01 Z0.1 (Tool offset 1 on) ;
M08 (Coolant on) ;
(BEGIN CUTTING BLOCKS) ;
G01 Z-1. F50. (Feed to cutting depth) ;
G41 G01 X0 Y0 D01 F50. (2D Cutter Comp left on) ;
Y4.125 (Linear motion) ;
G02 X0.25 Y4.375 R0.375 (Corner rounding) ;
G01 X1.6562 (Linear motion) ;
G02 X2. Y4.0313 R0.3437 (Corner rounding) ;
G01 Y3.125 (Linear motion) ;
G03 X2.375 Y2.75 R0.375 (Corner rounding) ;
G01 X3.5 (Linear motion) ;
G02 X4. Y2.25 R0.5 (Corner rounding) ;
G01 Y0.4375 (Linear motion) ;
G02 X3.4375 Y-0.125 R0.5625 (Corner rounding) ;
;
G01 X-0.125 (Linear motion) ;
G40 X-1. Y-1. (Last position, cutter comp off) ;
(BEGIN COMPLETION BLOCKS) ;
G00 Z0.1 M09 (Rapid retract, Coolant off) ;
G53 G49 Z0 M05 (Z home, Spindle off) ;
G53 Y0 (Y home) ;
M30 (End program) ;
%
```

**\*\*\*See Sample Program on USB Drive; O40006.NC**

## EXAMPLE OF TOOL MANUFACTURE'S TECHNICAL INFORMATION

### HARVI II TE APPLICATION DATA - Inch


| Material Group |    |  |  |        |      |          | Recommended Feed per Tooth (IPT=Inch/th) is for Side Milling . For Slotting Reduce Fz by 20% |        |               |        |        |        |        |        |        |        |        |        |        |        |  |  |
|----------------|----|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|--------|------|----------|----------------------------------------------------------------------------------------------|--------|---------------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|--|--|
|                |    |                                                                                   |                                                                                   |        |      |          | KCPM15A - KCSM15A                                                                            |        |               |        |        |        |        |        |        |        |        |        |        |        |  |  |
|                |    |                                                                                   |                                                                                   |        |      |          | Cutting Speed Vc                                                                             |        |               |        |        |        |        |        |        |        |        |        |        |        |  |  |
|                |    |                                                                                   |                                                                                   |        |      |          |                                                                                              |        | D1 - Diameter |        |        |        |        |        |        |        |        |        |        |        |  |  |
| Side Milling   |    | Slotting                                                                          |                                                                                   | SFM    |      | Fraction | 1/8                                                                                          | 5/32   | 3/16          | 7/32   | 1/4    | 9/32   | 5/16   | 3/8    | 1/2    | 5/8    | 3/4    | 1      | 1 1/4  |        |  |  |
| Ap Ae          |    | Ap                                                                                | Min                                                                               | Max    | dec. | 0.1250   | 0.1563                                                                                       | 0.1875 | 0.2188        | 0.2500 | 0.2813 | 0.3125 | 0.3750 | 0.5000 | 0.6250 | 0.7500 | 1.0000 | 1.2500 |        |        |  |  |
| P              | P0 | 1.5xD                                                                             | 0.5XD                                                                             | 1.25xD | 490  | 660      | IPT                                                                                          | 0.0010 | 0.0012        | 0.0015 | 0.0017 | 0.0020 | 0.0023 | 0.0026 | 0.0030 | 0.0037 | 0.0043 | 0.0048 | 0.0054 | 0.0054 |  |  |
|                | P1 | 1.5xD                                                                             | 0.5XD                                                                             | 1.25xD | 490  | 660      | IPT                                                                                          | 0.0010 | 0.0012        | 0.0015 | 0.0017 | 0.0020 | 0.0023 | 0.0026 | 0.0030 | 0.0037 | 0.0043 | 0.0048 | 0.0054 | 0.0054 |  |  |
|                | P2 | 1.5xD                                                                             | 0.5XD                                                                             | 1.25xD | 460  | 620      | IPT                                                                                          | 0.0010 | 0.0012        | 0.0015 | 0.0017 | 0.0020 | 0.0023 | 0.0026 | 0.0030 | 0.0037 | 0.0043 | 0.0048 | 0.0054 | 0.0054 |  |  |
|                | P3 | 1.5xD                                                                             | 0.5XD                                                                             | 1.25xD | 390  | 520      | IPT                                                                                          | 0.0008 | 0.0010        | 0.0012 | 0.0014 | 0.0017 | 0.0019 | 0.0021 | 0.0025 | 0.0032 | 0.0038 | 0.0042 | 0.0050 | 0.0053 |  |  |
|                | P4 | 1.5xD                                                                             | 0.5XD                                                                             | 1.25xD | 300  | 490      | IPT                                                                                          | 0.0007 | 0.0009        | 0.0011 | 0.0013 | 0.0015 | 0.0017 | 0.0019 | 0.0022 | 0.0028 | 0.0033 | 0.0037 | 0.0042 | 0.0044 |  |  |
|                | P5 | 1.5xD                                                                             | 0.5XD                                                                             | 1.25xD | 200  | 330      | IPT                                                                                          | 0.0007 | 0.0008        | 0.0010 | 0.0012 | 0.0014 | 0.0015 | 0.0017 | 0.0020 | 0.0025 | 0.0030 | 0.0034 | 0.0040 | 0.0043 |  |  |
| M              | P6 | 1.5xD                                                                             | 0.5XD                                                                             | 1.25xD | 160  | 250      | IPT                                                                                          | 0.0006 | 0.0007        | 0.0008 | 0.0010 | 0.0011 | 0.0013 | 0.0014 | 0.0017 | 0.0021 | 0.0025 | 0.0027 | 0.0031 | 0.0032 |  |  |
|                | M1 | 1.5xD                                                                             | 0.5XD                                                                             | 1.25xD | 300  | 380      | IPT                                                                                          | 0.0008 | 0.0010        | 0.0012 | 0.0014 | 0.0017 | 0.0019 | 0.0021 | 0.0025 | 0.0032 | 0.0038 | 0.0042 | 0.0050 | 0.0053 |  |  |
|                | M2 | 1.5xD                                                                             | 0.5XD                                                                             | 1.25xD | 200  | 260      | IPT                                                                                          | 0.0007 | 0.0008        | 0.0010 | 0.0012 | 0.0014 | 0.0015 | 0.0017 | 0.0020 | 0.0025 | 0.0030 | 0.0034 | 0.0040 | 0.0043 |  |  |
| K              | M3 | 1.5xD                                                                             | 0.5XD                                                                             | 1.0xD  | 200  | 230      | IPT                                                                                          | 0.0006 | 0.0007        | 0.0008 | 0.0010 | 0.0011 | 0.0013 | 0.0014 | 0.0017 | 0.0021 | 0.0025 | 0.0027 | 0.0031 | 0.0032 |  |  |
|                | K1 | 1.5xD                                                                             | 0.5XD                                                                             | 1.0xD  | 390  | 490      | IPT                                                                                          | 0.0010 | 0.0012        | 0.0015 | 0.0017 | 0.0020 | 0.0023 | 0.0026 | 0.0030 | 0.0037 | 0.0043 | 0.0048 | 0.0054 | 0.0054 |  |  |
|                | K2 | 1.5xD                                                                             | 0.5XD                                                                             | 1.0xD  | 360  | 460      | IPT                                                                                          | 0.0008 | 0.0010        | 0.0012 | 0.0014 | 0.0017 | 0.0019 | 0.0021 | 0.0025 | 0.0032 | 0.0038 | 0.0042 | 0.0050 | 0.0053 |  |  |
| S              | K3 | 1.5xD                                                                             | 0.5XD                                                                             | 1.0xD  | 360  | 430      | IPT                                                                                          | 0.0007 | 0.0008        | 0.0010 | 0.0012 | 0.0014 | 0.0015 | 0.0017 | 0.0020 | 0.0025 | 0.0030 | 0.0034 | 0.0040 | 0.0043 |  |  |
|                | S1 | 1.5xD                                                                             | 0.3XD                                                                             | 0.75xD | 160  | 300      | IPT                                                                                          | 0.0008 | 0.0010        | 0.0012 | 0.0014 | 0.0017 | 0.0019 | 0.0021 | 0.0025 | 0.0032 | 0.0038 | 0.0042 | 0.0050 | 0.0053 |  |  |
|                | S2 | 1.5xD                                                                             | 0.3XD                                                                             | 0.75xD | 80   | 160      | IPT                                                                                          | 0.0004 | 0.0005        | 0.0007 | 0.0008 | 0.0009 | 0.0010 | 0.0011 | 0.0013 | 0.0017 | 0.0020 | 0.0023 | 0.0027 | 0.0029 |  |  |
|                | S3 | 1.5xD                                                                             | 0.5XD                                                                             | 0.75xD | 80   | 130      | IPT                                                                                          | 0.0004 | 0.0005        | 0.0007 | 0.0008 | 0.0009 | 0.0010 | 0.0011 | 0.0013 | 0.0017 | 0.0020 | 0.0023 | 0.0027 | 0.0029 |  |  |
| H              | S4 | 1.5xD                                                                             | 0.5XD                                                                             | 1.25xD | 160  | 200      | IPT                                                                                          | 0.0005 | 0.0007        | 0.0008 | 0.0010 | 0.0012 | 0.0014 | 0.0016 | 0.0019 | 0.0023 | 0.0028 | 0.0031 | 0.0036 | 0.0039 |  |  |
|                | H1 | 1.5xD                                                                             | 0.5XD                                                                             | 1.0xD  | 260  | 460      | IPT                                                                                          | 0.0007 | 0.0009        | 0.0011 | 0.0013 | 0.0015 | 0.0017 | 0.0019 | 0.0022 | 0.0028 | 0.0033 | 0.0037 | 0.0042 | 0.0044 |  |  |
|                | H2 | 1.5xD                                                                             | 0.2XD                                                                             | 1.0xD  | 230  | 390      | IPT                                                                                          | 0.0006 | 0.0007        | 0.0008 | 0.0010 | 0.0011 | 0.0013 | 0.0014 | 0.0017 | 0.0021 | 0.0025 | 0.0027 | 0.0031 | 0.0032 |  |  |

### HARVI II TE APPLICATION DATA - Inch

| Material Group |    | Helical Interpolation / Ramping<br>15° - 30° |  |     | Min - Max Diameter for Helical Interpolation | Recommended feed per tooth (IPT = Inch/th) for Helical Interpolation and Ramping - Zef=2 |        |             |             |             |             |             |             |             |             |             |              |              |               |
|----------------|----|----------------------------------------------|-----------------------------------------------------------------------------------|-----|----------------------------------------------|------------------------------------------------------------------------------------------|--------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|--------------|--------------|---------------|
|                |    |                                              | KCPM15A - KCSM15A                                                                 |     |                                              | D1 - Diameter                                                                            |        |             |             |             |             |             |             |             |             |             |              |              |               |
|                |    |                                              | Cutting Speed Vc                                                                  |     |                                              |                                                                                          |        |             |             |             |             |             |             |             |             |             |              |              |               |
|                |    |                                              | SFM                                                                               |     |                                              |                                                                                          |        |             |             |             |             |             |             |             |             |             |              |              |               |
|                |    |                                              | Max Depth                                                                         | Min |                                              | Max                                                                                      | dec    | .144 - .238 | .179 - .296 | .216 - .356 | .251 - .415 | .288 - .475 | .323 - .534 | .359 - .594 | .431 - .713 | .575 - .950 | .719 - 1.188 | .863 - 1.425 | 1.150 - 1.900 |
|                |    |                                              |                                                                                   |     | 0.1250                                       | 0.1563                                                                                   | 0.1875 | 0.2188      | 0.2500      | 0.2813      | 0.3125      | 0.3750      | 0.5000      | 0.6250      | 0.7500      | 1.0000      | 1.2500       |              |               |
| P              | P0 | 1,25 x D1                                    | 490                                                                               | 660 | IPT                                          | 0.0007                                                                                   | 0.0009 | 0.0011      | 0.0013      | 0.0015      | 0.0017      | 0.0019      | 0.0022      | 0.0028      | 0.0033      | 0.0036      | 0.0040       | 0.0041       |               |
|                | P1 | 1,25 x D1                                    | 490                                                                               | 660 | IPT                                          | 0.0007                                                                                   | 0.0009 | 0.0011      | 0.0013      | 0.0015      | 0.0017      | 0.0019      | 0.0022      | 0.0028      | 0.0033      | 0.0036      | 0.0040       | 0.0041       |               |
|                | P2 | 1,25 x D1                                    | 460                                                                               | 620 | IPT                                          | 0.0007                                                                                   | 0.0009 | 0.0011      | 0.0013      | 0.0015      | 0.0017      | 0.0019      | 0.0022      | 0.0028      | 0.0033      | 0.0036      | 0.0040       | 0.0041       |               |
|                | P3 | 1,25 x D1                                    | 390                                                                               | 520 | IPT                                          | 0.0006                                                                                   | 0.0008 | 0.0009      | 0.0011      | 0.0013      | 0.0014      | 0.0016      | 0.0019      | 0.0024      | 0.0028      | 0.0032      | 0.0037       | 0.0040       |               |
|                | P4 | 1,25 x D1                                    | 300                                                                               | 490 | IPT                                          | 0.0005                                                                                   | 0.0007 | 0.0008      | 0.0010      | 0.0011      | 0.0013      | 0.0014      | 0.0017      | 0.0021      | 0.0025      | 0.0028      | 0.0032       | 0.0033       |               |
|                | P5 | 1,25 x D1                                    | 200                                                                               | 330 | IPT                                          | 0.0005                                                                                   | 0.0006 | 0.0007      | 0.0009      | 0.0010      | 0.0012      | 0.0013      | 0.0015      | 0.0019      | 0.0023      | 0.0025      | 0.0030       | 0.0032       |               |
| K              | P6 | 1,25 x D1                                    | 160                                                                               | 250 | IPT                                          | 0.0004                                                                                   | 0.0005 | 0.0006      | 0.0007      | 0.0009      | 0.0010      | 0.0011      | 0.0013      | 0.0016      | 0.0018      | 0.0021      | 0.0023       | 0.0024       |               |
|                | K1 | 1,0 x D1                                     | 390                                                                               | 490 | IPT                                          | 0.0007                                                                                   | 0.0009 | 0.0011      | 0.0013      | 0.0015      | 0.0017      | 0.0019      | 0.0022      | 0.0028      | 0.0033      | 0.0036      | 0.0040       | 0.0041       |               |
|                | K2 | 1,0 x D1                                     | 360                                                                               | 460 | IPT                                          | 0.0006                                                                                   | 0.0008 | 0.0009      | 0.0011      | 0.0013      | 0.0014      | 0.0016      | 0.0019      | 0.0024      | 0.0028      | 0.0032      | 0.0037       | 0.0040       |               |
| S              | K3 | 1,0 x D1                                     | 360                                                                               | 430 | IPT                                          | 0.0005                                                                                   | 0.0006 | 0.0007      | 0.0009      | 0.0010      | 0.0012      | 0.0013      | 0.0015      | 0.0019      | 0.0023      | 0.0025      | 0.0030       | 0.0032       |               |
|                | S1 | 0,75 x D1                                    | 160                                                                               | 300 | IPT                                          | 0.0006                                                                                   | 0.0008 | 0.0009      | 0.0011      | 0.0013      | 0.0014      | 0.0016      | 0.0019      | 0.0024      | 0.0028      | 0.0032      | 0.0037       | 0.0040       |               |
|                | S2 | 0,75 x D1                                    | 80                                                                                | 160 | IPT                                          | 0.0003                                                                                   | 0.0004 | 0.0005      | 0.0006      | 0.0007      | 0.0008      | 0.0009      | 0.0010      | 0.0013      | 0.0015      | 0.0017      | 0.0020       | 0.0022       |               |
|                | S3 | 0,5 x D1                                     | 80                                                                                | 130 | IPT                                          | 0.0003                                                                                   | 0.0004 | 0.0005      | 0.0006      | 0.0007      | 0.0008      | 0.0009      | 0.0010      | 0.0012      | 0.0014      | 0.0018      | 0.0021       | 0.0023       |               |
| H              | S4 | 1,25 x D1                                    | 160                                                                               | 200 | IPT                                          | 0.0004                                                                                   | 0.0005 | 0.0006      | 0.0008      | 0.0009      | 0.0010      | 0.0012      | 0.0014      | 0.0018      | 0.0021      | 0.0023      | 0.0027       | 0.0029       |               |
|                | H1 | 1,0 x D1                                     | 260                                                                               | 460 | IPT                                          | 0.0005                                                                                   | 0.0007 | 0.0008      | 0.0010      | 0.0011      | 0.0013      | 0.0014      | 0.0017      | 0.0021      | 0.0025      | 0.0028      | 0.0032       | 0.0033       |               |
|                | H2 | 1,0 x D1                                     | 230                                                                               | 390 | IPT                                          | 0.0004                                                                                   | 0.0005 | 0.0006      | 0.0007      | 0.0009      | 0.0010      | 0.0011      | 0.0013      | 0.0016      | 0.0018      | 0.0021      | 0.0023       | 0.0024       |               |

| LETTER CODE | MATERIAL GROUP                         |
|-------------|----------------------------------------|
| P           | STEEL                                  |
| M           | STAINLESS STEEL                        |
| K           | CAST IRON                              |
| N           | NONFERROUS (ALUMINUM, MAGNESIUM, ETC.) |
| S           | SUPERALLOYS (TITANIUM, ETC.)           |
| H           | HARDENED STEEL                         |

## CUTTER COMPENSATION EXERCISE 1




| Tool                                                                                | Description       | Diameter   | Flutes | SFM | Chip Load  |
|-------------------------------------------------------------------------------------|-------------------|------------|--------|-----|------------|
|  | H2TE5SE0500S063HA | 0.5 (1/2)  | 5      | 500 | 0.0037 IPT |
| Material                                                                            |                   | P0 - STEEL |        |     |            |

\*\*\* Calculate **Speed** ( $RPM = 3.82 \times SFM / DIA$ ) and **Feed** ( $IPM = FTP \times T \times RPM$ )

\*\*\* Outside Part Profile Tool Path

| HAAS Simulator: Go to MDI Mode:           | Save Program Referencing Page Number |
|-------------------------------------------|--------------------------------------|
| G00 G90 G17 G40 G49 G54                   |                                      |
| T1 M06                                    |                                      |
| S _____ M03                               |                                      |
| G43 H _____                               |                                      |
| X-0.5 Y-0.5                               |                                      |
| Z1.0                                      |                                      |
| M08                                       |                                      |
| G01 Z-0.5 F10. (Feed down to Z Depth)     |                                      |
| G41 F _____ D _____ G01 X _____ Y _____ → |                                      |
| ...                                       |                                      |
| ...                                       |                                      |
| M30                                       |                                      |
| Run program in Graphic Mode.              |                                      |

## CUTTER COMPENSATION EXERCISE 2




| Tool                                                                                | Description       | Diameter   | Flutes | SFM | Chip Load  |
|-------------------------------------------------------------------------------------|-------------------|------------|--------|-----|------------|
|  | H2TE5SE0500S063HA | 0.5 (1/2)  | 5      | 500 | 0.0037 IPT |
| Material                                                                            |                   | P0 - STEEL |        |     |            |

\*\*\* Calculate **Speed** ( $RPM = 3.82 \times SFM / DIA$ ) and **Feed** ( $IPM = FTP \times T \times RPM$ )

| HAAS Simulator: Go to MDI Mode:                 | Save Program Referencing Page Number |
|-------------------------------------------------|--------------------------------------|
| G00 G90 G17 G40 G49 G54                         |                                      |
| T1 M06                                          |                                      |
| <b>S</b> _____ M03                              |                                      |
| G43 <b>H</b> _____                              |                                      |
| X-0.5 Y-0.5                                     |                                      |
| Z1.0                                            |                                      |
| M08                                             |                                      |
| G01 Z-0.5 F10. (Feed down to Z Depth)           |                                      |
| G41 <b>F</b> _____ <b>D</b> _____ G01 X__ Y__ → |                                      |
| ...                                             |                                      |
| ...                                             |                                      |
| M30                                             |                                      |
| Run program in Graphic Mode.                    |                                      |

### CUTTER COMPENSATION EXERCISE 3



| Tool                                                                                | Description        | Diameter         | Flutes | SFM | Chip Load |
|-------------------------------------------------------------------------------------|--------------------|------------------|--------|-----|-----------|
|  | H2TE5SE0281R075HAV | 0.3125<br>(5/16) | 5      | ??? | ???       |
| Material                                                                            |                    | P0 - STEEL       |        |     |           |


\*\*\* Choose **SFM** and **FPT** from Kennametal Tech Info chart.

\*\*\* Calculate **Speed** ( $RPM = 3.82 \times SFM / DIA$ ) and **Feed** ( $IPM = FTP \times T \times RPM$ )

\*\*\* Top part is symmetrical to bottom half. Use dimensions from the top half.

| HAAS Simulator: Go to MDI Mode:       | Save Program Referencing Page Number |
|---------------------------------------|--------------------------------------|
| G00 G90 G17 G40 G49 G54               |                                      |
| T1 M06                                |                                      |
| S ____ M03                            |                                      |
| G43 H ____                            |                                      |
| X-0.5 Y-0.5                           |                                      |
| Z1.0                                  |                                      |
| M08                                   |                                      |
| G01 Z-0.5 F10. (Feed down to Z Depth) |                                      |
| G41 F ____ D ____ G01 X ____ Y ____ → |                                      |
| ...                                   |                                      |
| ...                                   |                                      |
| M30                                   |                                      |
| Run program in Graphic Mode.          |                                      |

## CUTTER COMPENSATION EXERCISE 4



| Tool                                                                                | Description       | Diameter       | Flutes | SFM | Chip Load |
|-------------------------------------------------------------------------------------|-------------------|----------------|--------|-----|-----------|
|  | H2TE5SE0375S075HA | 0.375<br>(3/8) | 5      | ??? | ???       |
| Material                                                                            |                   | P0 - STEEL     |        |     |           |

\*\*\* Choose **SFM** and **FPT** from Kennametal Tech Info chart.

\*\*\* Calculate **Speed** ( $RPM = 3.82 \times SFM / DIA$ ) and **Feed** ( $IPM = FTP \times T \times RPM$ )

\*\*\* This is an **extra Exercise**. Sharp corners will be **round off** based on the tool diameter.

| HAAS Simulator: Go to MDI Mode:       | Save Program Referencing Page Number |
|---------------------------------------|--------------------------------------|
| G00 G90 G17 G40 G49 G54               |                                      |
| T1 M06                                |                                      |
| S ____ M03                            |                                      |
| G43 H ____                            |                                      |
| X-0.5 Y-0.5                           |                                      |
| Z1.0                                  |                                      |
| M08                                   |                                      |
| G01 Z-0.5 F10. (Feed down to Z Depth) |                                      |
| G41 F ____ D ____ G01 X__ Y__ →       |                                      |
| ...                                   |                                      |
| ...                                   |                                      |
| M30                                   |                                      |
| Run program in Graphic Mode.          |                                      |

## G12 CIRCULAR POCKET MILLING CW / G13 CIRCULAR POCKET MILLING CCW (GROUP 00)

These G-codes mill circular shapes. **G12** cuts in a clockwise direction, while **G13** cuts counterclockwise. Both commands use the default **XY plane (G17)** and automatically apply cutter compensation—**G42** for G12 and **G41** for G13. Both G-codes are **non-modal**.

\* **D** - Tool radius or diameter selection\*\*

**F** - Feedrate

**I** - Radius of first circle (or finish if no **K**). **I** value must be greater than Tool Radius, but less than **K** value.

\* **K** - Radius of finished circle (if specified)

\* **L** - Loop count for repeating deeper cuts

\* **Q** - Radius increment, or stepover (must be used with **K**)

**Z** - Depth of cut or increment

\*Indicates optional

\*\* To calculate the programmed circle diameter, the control uses the tool size associated with the selected **D**-code. To program the tool centerline, specify **D0**.




### NOTE

Specify **D00** if you do not want to use cutter compensation. If a **D** value is not specified in the **G12/G13** block, the control uses the last commanded **D** value, even if it was previously canceled with **G40**.

Rapid-position the tool to the center of the circle. To remove all material inside the circle, use **I** and **Q** values that are less than the tool diameter and a **K** value equal to the circle radius. To cut only the circle radius, use an **I** value set to the radius and do **not** specify **K** or **Q**.

---

**CIRCULAR POCKET MILLING, G12 CLOCKWISE SHOWN: [1] I ONLY, [2] I, K AND Q ONLY.**



**\*\*\* Program O60121 in G12 & G13 Sample Program Folder on USB Drive \*\*\***

These G-codes assume cutter compensation, so G41 or G42 do not need to be programmed in the block. However, a **D** offset number must be included to apply the cutter radius or diameter and adjust the circle diameter.

The following examples illustrate the **G12** and **G13** formats and the various ways they can be written.

**Single Pass:** Use **I** only.

**Applications:** One-pass counterboring; rough and finish pocketing of smaller holes; I.D. cutting of O-ring grooves.

**Multiple Pass:** Use **I, K, and Q**.

**Applications:** Multiple-pass counterboring; rough and finish pocketing of large holes with cutter overlap.

**Multiple Z-Depth Pass:** Use **I** only, or **I, K, and Q** (G91 and **L** may also be used).

**Applications:** Deep rough and finish pocketing.

The previous figures illustrate the toolpath produced by the pocket-milling G-codes.

---

**EXAMPLE G13 MULTIPLE-PASS USING I, K, Q, L, AND G91:**


**\*\*\* Program O60131 in G12 & G13 Sample Program Folder on USB Drive \*\*\***

This program uses G91 and an **L** count of 4, so this cycle will execute a total of four times. The Z depth increment is 0.500. This is multiplied by the **L** count, making the total depth of this hole 2.000.

The G91 and **L** count can also be used in a G13/ only line.

## G13 AND G12 (GROUP 00) EXERCISE

### Part Drawing



| Tool Information for G13 and G12 (Group 00) Exercise |                                                                                     |                                                         | Surface Feed | Chip Load |
|------------------------------------------------------|-------------------------------------------------------------------------------------|---------------------------------------------------------|--------------|-----------|
| Tool 1                                               |  | 1/2 (.5000) Dia, 4 Flt,<br>SE Square Carbide<br>Endmill | 250          | .0013 IPT |

\*\*\* Calculate **Speed** ( $RPM = 3.82 \times SFM / DIA$ ) and **Feed** ( $IPM = FTP \times T \times RPM$ )

\*\*\* Choose your origin (G54 – X0 Y0) on the part

\*\*\* Open 1.0" Bore to 3.0"

- Circular Pocket Milling G13 for ID to maintain climb milling
- Cutter comp is not required. Use Tool diameter for compensation.
- **Z Depths is -0.50"**

| HAAS Simulator: Go to MDI Mode:                | Save Program Referencing Page Number |
|------------------------------------------------|--------------------------------------|
| G00 G90 G17 G40 G49 G54 ( <b>Safety Line</b> ) | _____                                |
| T__ M06                                        | _____                                |
| S__ M03                                        | _____                                |
| G43 H__                                        | _____                                |
| X__ Y__                                        | _____                                |
| Z__                                            | _____                                |
| M08                                            | _____                                |
| G01 ____ → (Feed down to Z depth)              | _____                                |
| G13 D__ →                                      | _____                                |
| ...                                            | _____                                |
| M30                                            | _____                                |
| ...                                            | _____                                |
| Run program in Graphic Mode.                   | _____                                |

## CANNED CYCLES

Canned cycles are G-codes used for repetitive operations such as drilling, tapping, and boring. They are defined using alphabetic address codes, and while the cycle is active, the machine performs the specified operation each time a new position is commanded—unless otherwise directed.

Canned cycles simplify programming because most common Z-axis repetitive operations use them. Once active, the cycle executes at every new axis location. Axis motion occurs in rapid mode (**G00**), and the canned cycle action is performed after the move. This applies to **G17** and **G19** plane cycles, as well as Y-axis movements on Y-axis lathes.

### DRILLING CANNED CYCLES

All four drill canned cycles can be looped when using **G91**, Incremental Programming mode.

- **G81 Drill Canned Cycle** is the basic drilling cycle. It is used for drilling shallow holes or for drilling with Through-Spindle Coolant (TSC).
- **G82 Spot Drill Canned Cycle** operates the same as G81 but includes an optional dwell at the bottom of the hole. The **P** address specifies the dwell duration.
- **G83 Normal Peck Drilling Canned Cycle** is typically used for deep holes. Peck depth may be variable or constant, and it is always incremental. Use **Q** for peck depth, but do **not** use **Q** with **I**, **J**, or **K** values.
- **G73 High-Speed Peck Drilling Canned Cycle** is similar to G83, except that peck retraction is controlled by **Setting 22 – Can Cycle Delta Z**. Peck drilling is recommended for holes deeper than three times the drill diameter. The initial peck depth (**I**) should generally equal one tool diameter.

### TAPPING CANNED CYCLES

There are two tapping canned cycles, and both can be looped when using **G91**, Incremental Programming mode.

- **G84 Tapping Canned Cycle** is the standard tapping cycle used for cutting **right-hand threads**.
- **G74 Reverse Tap Canned Cycle** is used for tapping **left-hand threads**.

## BORING AND REAMING CYCLES

There are five boring canned cycles, and all of them can be looped when using **G91**, Incremental Programming mode.

- **G85 Boring Canned Cycle** is the basic boring cycle. It bores to the programmed depth and then returns to the specified height.
- **G86 Bore and Stop Canned Cycle** functions like G85, except the spindle stops at the bottom of the hole before the tool retracts.
- **G89 Bore In, Dwell, Bore Out Canned Cycle** is similar to G85 but includes a dwell at the bottom of the hole. During retraction, the tool continues boring at the programmed feedrate rather than retracting in rapid or jog mode, as other boring cycles do.
- **G76 Fine Boring Canned Cycle** bores to the programmed depth, then moves to clear the tool from the hole before retracting.
- **G77 Back Bore Canned Cycle** operates similarly to G76, but it first moves the tool to clear the hole, then positions it inside the hole before boring to depth.

## R PLANES

**R planes** (return planes) specify the Z-axis return height used during canned cycles.

R-plane commands remain active for the duration of the canned cycle in which they are used. **G98** (Canned Cycle Initial Point Return) returns the Z-axis to the height it was at before the canned cycle began.

**G99** (Canned Cycle R-Plane Return) returns the Z-axis to the height specified by the **R** value programmed in the canned cycle block.

## CANNED CYCLES G81 AND G82

Canned cycles automate a series of movements and reduce the amount of code required. These cycles apply only to **Z-axis** operations, while **X** and **Y** (in **G17**) specify the hole location. The next commanded position may use either **G90** (absolute) or **G91** (incremental) positioning. **G98** (Canned Cycle Initial Point Return) and **G99** (Canned Cycle R-Plane Return) control the Z-axis return height, and both are modal commands.

**G80** (Canned Cycle Cancel) must be used to cancel the cycle after completion.

See the sample program below for examples using **G90** and **G91** movements.

\*\*\* Program O34000 in G91 Looping Canned Cycle Sample Program Folder on USB Drive \*\*\*

### G81 DRILL CANNED CYCLE (GROUP 09)

- \* **E** - Chip-clean RPM (Spindle reverses to remove chips after each cycle)
- F** - Feedrate
- \* **L** - Number of holes to drill if **G91** (Incremental Mode) is used
- \* **R** - Position of the R plane (position above the part)
- \* **X** - X-Axis motion command
- \* **Y** - Y-Axis motion command
- Z** - Position of the Z Axis at the bottom of hole


\* indicates optional



#### CAUTION

Unless otherwise specified, this canned cycle uses the most recently commanded spindle direction (M03, M04, or M05). If no spindle direction is commanded beforehand, the machine defaults to M03 (clockwise). If M05 is active, the cycle runs with no spindle rotation, which is appropriate for self-driven tools but may cause a crash in other situations. Always verify spindle direction before using this canned cycle.

### G81 Drill Canned Cycle



This is a program to drill through an aluminum plate:

\*\*\* Program is in G81 Sample Program Folder on USB Drive \*\*\*

## G82 SPOT DRILL CANNED CYCLE (GROUP 09)

- \* **E** - Chip-clean RPM (Spindle reverses to remove chips after each cycle)
- F** - Feedrate
- \* **L** - Number of holes if G91 (Incremental Mode) is used.
- \* **P** - The dwell time at the bottom of the hole
- \* **R** - Position of the R plane (position above the part)
- \* **X** - X-Axis location of hole
- \* **Y** - Y-Axis location of hole
- Z** - Position of bottom of hole

\* indicates optional



### NOTE

The **P** values are modal. This means that if a **G04 Pnn** or an **M97 Pnn** is used during a canned cycle, the **P** value will apply to the dwell or subprogram as well as the canned cycle.




### CAUTION

Unless otherwise specified, this canned cycle uses the most recently commanded spindle direction (M03, M04, or M05). If no spindle direction is commanded beforehand, the machine defaults to M03 (clockwise). If M05 is active, the cycle runs with no spindle rotation, which is appropriate for self-driven tools but may cause a crash in other situations. Always verify spindle direction before using this canned cycle.



### NOTE



G82 is similar to G81 except that there is the option to program a dwell ( **P** ).



**G82 Spot Drilling Example**

**\*\*\* Program is in G82 Sample Program Folder on USB Drive \*\*\***

[illegible]



| Tool Information for G81 and G82 Canned Cycle Exercise |                                                                                   |                                                   | Surface Feed | Chip Load |
|--------------------------------------------------------|-----------------------------------------------------------------------------------|---------------------------------------------------|--------------|-----------|
| Tool 1                                                 |  | 3/8 (.3750) Dia, 2 Flt, Screw Machine             | 100          | .007 IPR  |
| Tool 2                                                 |  | HSS Countersink, 3/4 (.7500) Dia, 82 Degree       | 60           | .005 IPR  |
| Tool 3                                                 |  | 1/2 (.5000) Dia, 4 Flt, SE Square Carbide Endmill | 250          | .0013 IPT |

\*\*\* Calculate **Speed** ( $RPM = 3.82 \times SFM / DIA$ ) and **Feed** ( $IPM = FTP \times T \times RPM$ ) / ( $IPM = IPR \times RPM$ )

\*\*\* Put a **0.020"** Chamfer on Counter Bore using **Drill Point Depth and Countersink Diameter**

**Formula from HAAS Machinist Handbook**

**Operation Order:**

1. **Drill with Tool 1 (G81)**
2. **Counter Bore with Tool 3 (G81 or G82) \*\*\* G82 allows you to dwell at Z depth.**
3. **Chamfer holes with Tool 2 using formula from HAAS Machinist Handbook**

| HAAS Simulator: Go to MDI Mode:         | Save Program Referencing Page Number |
|-----------------------------------------|--------------------------------------|
| G00 G90 G17 G40 G49 G54 ( <b>Safety</b> |                                      |
| <b>Line)</b>                            |                                      |
| T__ M06                                 |                                      |
| G43 H__                                 |                                      |
| S__ M03                                 |                                      |
| X__ Y__                                 |                                      |
| Z5.0                                    |                                      |
| M08                                     |                                      |
| G01 ____ →                              |                                      |
| ...                                     |                                      |
| G81 ...                                 |                                      |
| ...                                     |                                      |
| G82 ...                                 |                                      |
| ...                                     |                                      |
| G81 ...                                 |                                      |
| ...                                     |                                      |
| M30                                     |                                      |
| Run program in Graphic Mode.            |                                      |
|                                         |                                      |
|                                         |                                      |
|                                         |                                      |
|                                         |                                      |
|                                         |                                      |
|                                         |                                      |
|                                         |                                      |
|                                         |                                      |
|                                         |                                      |
|                                         |                                      |

## G83 NORMAL PECK DRILLING CANNED CYCLE (GROUP 09)

- \* **E** - Chip-clean RPM (Spindle reverses to remove chips after each cycle)
- F** - Feedrate
- \* **I** - Size of first peck depth
- \* **J** - Amount to reduce peck depth each pass
- \* **K** - Minimum depth of peck
- \* **L** - Number of holes if **G91** (Incremental Mode) is used, also **G81** through **G89**.
- \* **P** - Pause at end of last peck, in seconds (Dwell)
- \* **Q** - Peck depth, always incremental
- \* **R** - Position of the R plane (position above the part)
- \* **X** - X-Axis location of hole
- \* **Y** - Y-Axis location of hole
- Z** - Position of the Z-Axis at the bottom of hole


\* Indicates optional

If **I**, **J**, and **K** are specified, the first pass will cut in by the amount of **I**, each succeeding pass will be reduced by **J**, and the minimum cutting depth is **K**. Do **not** use a **Q** value when programming with **I**, **J**, and **K**.


If **P** is specified, the tool will pause at the bottom of the hole for the programmed duration. For example, the following block will peck several times and include a 1.5-second dwell:

```
G83 Z-0.62 F15. R0.1 Q0.175 P1.5 ;
```

The same dwell time applies to all subsequent blocks that do not specify a new **\*\*P\*\*** value.




**Setting 52** modifies how **G83** handles retracts to the **R-plane**. Normally, the R-plane is positioned well above the part so each peck retract clears chips, but this also adds unnecessary travel as the tool repeatedly re-enters empty space. When Setting 52 is set to the minimum distance required for chip clearance, the R-plane can be set closer to the part. During chip-clearing retracts, Setting 52 determines how far above the programmed R-plane the Z-axis retracts.



**G83 peck Drilling Canned Cycle with Setting 52 [#52]**

**\*\*\* Program is in G83 Sample Program Folder on USB Drive \*\*\***





- \* **E** - Chip-clean RPM (Spindle reverses to remove chips after each cycle)
- F** - Feedrate
- \* **J** - Retract Multiple (Example: *J2* retracts twice as fast as the cutting speed, also refer to Setting 130)
- \* **L** - Number of holes if *G91* (Incremental Mode) is used
- \* **R** - Position of the R plane (Position above the part)
- \* **X** - X-Axis location of hole
- \* **Y** - Y-Axis location of hole
- Z** - Position of the Z Axis at the bottom of hole
- \* **Q** - Peck Depth (always incremental)
- \* **S** - Spindle speed


\* Indicates optional



#### NOTE

You do not need to command a spindle start (M03/M04) before G84. The canned cycle automatically starts and stops the spindle as required.

### G84 Tapping Canned Cycle



\*\*\* Program is in G84 Sample Program Folder on USB Drive \*\*\*

## G70 / G71 / G72 BOLT HOLE PATTERN

**G70**, **G71**, and **G72** are use with Canned Cycles. Must execute Canned cycle first before providing Bolt hole pattern.

Example below Uses **G81** with **G71** Bolt Hole Pattern.


**G00 X0 Y0**

**Z5.0**

**G81 Z-0.5 R0.1 F10.0**

**G71 I3.0 J15.0 K30.0 L5.0**

(L5) Number of holes



### Rules for Bolt Pattern Canned Cycles

1. Position the tool at the center of the bolt pattern (G70 or G71) or at the starting hole location (G72) before executing the canned cycle.
2. The J code defines the starting angle and is always specified from 0° to 360°, measured counterclockwise from the three-o'clock position.
3. For G70 and G71, program **L0** on the initial canned-cycle line to skip drilling at the center of the pattern. Alternatively, disabling Setting 28 prevents drilling at the initial X/Y location. Refer to *Setting 28 – Can Cycle No Linear Axes* for details.

---

## G70 BOLT HOLE CIRCLE (GROUP 00)


I - Radius

\* J - Starting angle (0 to 360.0 degrees CCW from horizontal;

or 3 o'clock position)

L - Number of holes evenly spaced around the circle

\*Indicates optional



---

## G71 BOLT HOLE ARC (GROUP 00)


I - Radius

\* J - Starting angle (degrees CCW from horizontal)

K - Angular spacing of holes (+ or --)

L - Number of holes

\*Indicates optional



---


## G72 BOLT HOLES ALONG AN ANGLE (GROUP 00)

I - Distance between holes



\* J - Angle of line (degrees CCW from horizontal)

L - Number of holes


\*Indicates optional



[illegible]









## G73 HIGH-SPEED PECK DRILLING CANNED CYCLE (GROUP 09)

**F** - Feedrate

\* **I** - First peck depth

\* **J** - Amount to reduce pecking depth for pass

\* **K** - Minimum peck depth (The control calculates the number of pecks)

\* **L** - Number of loops (Number of holes to drill) if G91 (Incremental Mode) is used

\* **P** - Pause at the bottom of the hole (in seconds)

\* **Q** - Peck Depth (always incremental)

\* **R** - Position of the R plane (Distance above part surface)

\* **X** - X-Axis location of hole

\* **Y** - Y-Axis location of hole

**Z** - Position of the Z-Axis at the bottom of hole

\* indicates optional




**NOTE**

The P values are modal. This means if you are in the middle of a canned cycle and a G04 Pnn or an M97 Pnn is used the P value will be used for the dwell / subprogram as well as the canned cycle.

**G73 Peck Drilling. Left: Using I, J, and K Addresses. Right: Using Only the Q Address. [#22] Setting 22.**


I, J, K, and Q are always positive values.

There are three methods for programming a G73 cycle: using the I, J, and K addresses; using the K and Q addresses; or using only a Q address.



When I, J, and K are specified, the first peck advances by I, each subsequent peck is reduced by J, and K defines the minimum peck depth. If a P value is included, the tool dwells at the bottom of the hole for the programmed duration.

When K and Q are both specified, the cycle operates in an alternate mode in which the tool returns to the R-plane after the cumulative peck depth reaches the K value.




When only Q is specified, the cycle uses a uniform peck depth. The tool returns to the R-plane only after all pecks are completed.

## G98 CANNED CYCLE INITIAL POINT RETURN (GROUP 10)

Using **G98**, the Z-axis returns to its initial starting point (the Z-position from the block before the canned cycle) between each X/Y move. This allows the tool to clear part features, clamps, and other obstructions.

In the example, after drilling the second hole, the Z-axis returns to the initial Z position under **G98** so the tool can safely move over the toe clamp to the next hole location.

\*\*\* Program is in G98 Sample Program Folder on USB Drive \*\*\*




## G99 CANNED CYCLE R PLANE RETURN (GROUP 10)

Using **G99**, the Z-axis remains at the programmed R-plane between each X/Y move. When there are no obstructions in the toolpath, **G99** reduces unnecessary motion and shortens cycle time.

In the example, after the first hole, the Z-axis returns to the R-plane under **G99** and moves to the second hole location. This is safe in this case because no obstacles are present.



\*\*\* Program is in G99 Sample

Program Folder on USB Drive \*\*\*



## FINAL EXERCISE (OPTIONAL)

### Part Drawing



| Tool Information for Final Exercise |                                                                                   |                                                         | Surface Feed | Chip Load |
|-------------------------------------|-----------------------------------------------------------------------------------|---------------------------------------------------------|--------------|-----------|
| Tool 1                              |  | HSS Countersink,<br>3/4 (.7500) Dia, 82<br>Degree       | 60           | .005 IPR  |
| Tool 2                              |  | 1/2 (.5000) Dia, 2 Flt,<br>2.0000 LOC                   | 100          | .010 IPR  |
| Tool 3                              |  | 3/8 (.3750) Dia, 2 Flt,<br>Screw Machine                | 100          | .007 IPR  |
| Tool 4                              |  | 1/2 (.5000) Dia, 4 Flt,<br>SE Square Carbide<br>Endmill | 250          | .0013 IPT |
| Tool 5                              |  | 90° Angle, .0050 Tip<br>Dia, .1250 Shank                | 60           | .001 IPT  |

\*\*\* Create part using Canned Cycles.

\*\*\* Outside Profile is optional.

\*\*\* Engraving using **G47**. Adjust TEXT to fit center of part.

\*\*\* **0.020"** Chamfer on all holes

\*\*\* Mill out circular pockets using **VPS**.

\*\*\* Calculate **Speed** ( $RPM = 3.82 \times SFM / DIA$ ) and **Feed** ( $IPM = FTP \times T \times RPM$ ) / ( $IPM = IPR \times RPM$ )

\*\*\* Choose your Origin on part

| HAAS Simulator: Go to MDI Mode:       | Save Program Referencing Page Number |
|---------------------------------------|--------------------------------------|
| G00 G90 G17 G40 G49 G54 (Safety Line) |                                      |
| T__ M06                               |                                      |
| S__ M03                               |                                      |
| X__ Y__                               |                                      |
| M08                                   |                                      |
| G43 H__ Z1.0                          |                                      |
| G01 __ →                              |                                      |
| ...                                   |                                      |
| ...                                   |                                      |
| ...                                   |                                      |
| ...                                   |                                      |
| M30                                   |                                      |
| Run program in Graphic Mode.          |                                      |
|                                       |                                      |
|                                       |                                      |
|                                       |                                      |
|                                       |                                      |
|                                       |                                      |
|                                       |                                      |
|                                       |                                      |

## G150 GENERAL PURPOSE POCKET MILLING (GROUP 00)

**D** - Tool radius/diameter offset selection

**F** - Feedrate

**I** - X-Axis cut increment (positive value)

**J** - Y-Axis cut increment (positive value)

**K** - Finishing pass amount (positive value)

**P** - Subprogram number that defines pocket geometry

**Q** - Incremental Z-Axis cut depth per pass (positive value)

\* **R** - Position of the rapid R-plane location

\* **S** - Spindle speed

**X** - X start position

**Y** - Y start position

**Z** - Final depth of pocket

\* Indicates optional

The **G150** cycle begins by positioning the cutter at a start point inside the pocket, then roughs the pocket outline and finishes with a final cleanup pass. The tool plunges in the Z-axis before pocketing. A subprogram (**P###**) defines the closed-geometry pocket shape using **G01**, **G02**, and **G03** motions in X and Y.

When **G150** is executed, the control first searches for an internal subprogram whose **N-number** matches the P-code. If none is found, it searches for an external subprogram. If the subprogram cannot be located, the control generates **Alarm 314 – Subprogram Not In Memory**.

**NOTE** Do not return to the starting point after closing the pocket geometry in the **G150** subprogram.

**NOTE** The pocket-geometry subprogram used with **G150** cannot contain macro variables.

An **I** or **J** value defines the roughing-pass stepover for each cut increment. **I** produces incremental cuts in the X-axis, while **J** produces incremental cuts in the Y-axis.

The **K** command defines the finish-pass allowance. When **K** is specified, the control makes a final finishing pass by the K amount around the inside of the pocket at the final Z-depth. There is no separate finishing-pass command for Z.

The **R** value must be specified—even **R0**—otherwise the control uses the last commanded R value.

Pocketing is performed in multiple passes, starting at the R-plane. With each **Q** depth increment, the tool feeds down and removes material until the final Z-depth is reached. **G150** first makes a contour pass leaving the K amount of stock, then performs roughing passes based on the I or J increment.


The **Q** command is required on the **G150** line, even if only a single pass to the final Z-depth is desired. The Q value is applied from the R-plane.

### Notes:

- The pocket-geometry subprogram (P) must not contain more than 40 geometry moves.
- A starting hole to full depth may be required before running **G150**. After drilling, position the end mill at the pocket's XY start point and then execute the **G150** command.

---

## G150 GENERAL POCKET MILLING: [1] START POINT, [Z] FINAL DEPTH.




**Main Program O61501** (G150 GENERAL POCKET MILLING)

**Sub Program O61502** (G150 GENERAL POCKET MILL SUBPROGRAM)

**\*\*\* Programs are in G150 Sample Programs Folder on USB Drive \*\*\***

## Square Pocket

**G150 GENERAL PURPOSE POCKET MILLING: 0.500 DIAMETER ENDMILL.**



## 5.0 x 5.0 x 0.500 DP. Square Pocket

**Main Program O61503** (G150 SQUARE POCKET MILLING)

**Subprogram O61505** (G150 INCREMENTAL SQUARE POCKET MILLING SUBPROGRAM)

**\*\*\* Programs are in G150 Sample Programs Folder on USB Drive \*\*\***

**ABSOLUTE AND INCREMENTAL EXAMPLES OF A SUBPROGRAM CALLED UP BY THE P#### COMMAND IN THE G150 LINE:**


**Absolute Subprogram O61504** (G150 ABSOLUTE SQUARE POCKET MILLING SUBPROGRAM)

**Incremental Subprogram O61511** (G150 INCREMENTAL SQUARE POCKET MILLING SUBPROGRAM);

**\*\*\* Programs are in G150 Sample Programs Folder on USB Drive \*\*\***

## SQUARE ISLAND

**G150 Pocket Milling Square Island: 0.500 diameter endmill.**



**5.0 x 5.0 x 0.500 DP. Square Pocket with Square Island**

**Main Program O61506** (G150 SQUARE ISLAND POCKET MILLING)


**Subprogram O61507** (G150 SQUARE ISLAND POCKET MILLING SUBPROGRAM)

**\*\*\* Programs are in G150 Sample Programs Folder on USB Drive \*\*\***

---

**ROUND ISLAND**

**G150 Pocket Milling Round Island: 0.500 diameter endmill.**



**5.0 x 5.0 x 0.500 DP. Square Pocket with Round Island**

**Main Program O61508** (G150 SQ POCKET W/ ROUND ISLAND MILLING)

**Subprogram O61509** (G150 SQ POCKET W/ ROUND ISLAND MILLING SUBPROGRAM)

**\*\*\* Programs are in G150 Sample Programs Folder on USB Drive \*\*\***

## SPECIAL G-CODES

Special G-codes are used for complex milling. These include:

- Engraving (G47)
- Pocket Milling (G12, G13, and G150)
- Rotation and Scaling (G68, G69, G50, G51)
- Mirror Image (G101 and G100)

### ENGRAVING

The G47 Text Engraving G-code lets you engrave text (including some ASCII characters) or sequential serial numbers with a single block of code.

Refer to G47 Text Engraving (Group 00) for more information on engraving.

### POCKET MILLING

There are two types of pocket milling G-codes on the Haas control:

Circular Pocket Milling is performed with the G12 Clockwise Circular Pocket Milling Command and the G13 Counter-Clockwise Circular Pocket Milling Command G-codes.

The G150 General Purpose Pocket Milling uses a subprogram to machine user-defined pocket geometries.

Make sure that the subprogram geometry is a fully closed shape. Make sure that the X-Y starting point in the G150 command is within the boundary of the fully closed shape. Failure to do so may cause Alarm 370 - Pocket Definition Error.

Refer to G12 Circular Pocket Milling CW / G13 Circular Pocket Milling CCW (Group 00) for more information on the pocket milling G-codes.

### ROTATION AND SCALING

**NOTE:** You must purchase the rotation and scaling option to use these features. A 200-hour option tryout is also available.

G68 Rotation is used to rotate the coordinate system in the desired plane. You can use this feature together with G91 Incremental Programming mode to machine symmetrical patterns. G69 cancels rotation.

G51 applies a scaling factor to the positioning values in blocks after the G51 command. G50 cancels scaling. You can use scaling together with rotation, but be sure to command scaling first. Refer to G68 Rotation (Group 16) for more information on the rotation and scaling G-codes.

## MIRROR IMAGE

G101 Enable Mirror Image will mirror axis motion about the specified axis. Settings 45-48, 80 and 250 enable mirror imaging about the X, Y, Z, A, B, and C axes.

The mirror pivot point along an axis is defined by the Xnn.nn argument. This can be specified for a Y Axis that is enabled on the machine and in the settings by using the axis to mirror as the argument. G100 cancels G101.

Refer to G100/G101 Disable/Enable Mirror Image (Group 00) for more information on the mirror image G-codes.

## ROTATION AND SCALING

Rotation lets you rotate a pattern to another location or around a circumference. Scaling reduces or enlarges a toolpath or pattern.

Refer to [G68 Rotation](#) to learn how to use this control feature.

## RIGID TAPPING

This option synchronizes the spindle's RPM with the feedrate during a tapping operation. Refer to [G84 Tapping Canned Cycle](#) to learn how to use this control feature.

Refer to [Tap Breakage - Troubleshooting guide](#) to view solutions to some of the most common causes for tap breakage.

## M19 SPINDLE ORIENTATION

The Spindle Orientation lets you position the spindle to a programmed angle. This option provides inexpensive, accurate positioning.

Refer to the [M19 Orient Spindle](#) for more information on how to use this software control feature.

## HIGH-SPEED MACHINING

The Haas high-speed machining option allows faster feedrates and more complex toolpaths.

HSM uses a motion algorithm called Acceleration Before Interpolation combined with full look-ahead to provide contouring feeds up to 1200 ipm (30.5 m/min) without risk of distortion to the programmed path.

This reduces cycle times, improves accuracy, and smooths motion.

Refer to [G187 Accuracy Control](#) to control the smoothness and max corner rounding value when cutting a part.

## SUBPROGRAMS

### Subprograms:

- Are usually a series of commands that are repeated several times in a program.
- Are written in a separate program, instead of repeating the commands many times in the main program.
- Are called in the main program with an M97 or M98 and a P code.
- Can include an L for repeat count. The subprogram call repeats L times before the main program continues with the next block.

### When you use M97:

- The P code (nnnnn) is the same as the block number (Nnnnnn) of the local subprogram.
- The subprogram must be within the main program

### When you use M98:

- The P code (nnnnn) is the same as the program number (Onnnnn) of the subprogram.
- If the subprogram is not in memory, the file name must be Onnnnn.nc. The file name must contain the O, leading zeros and .nc for the machine to find the subprogram.
- The subprogram must reside in the active directory, or in a location specified in Settings 251/252. Refer to page 5 for more information on subprogram search locations.
- Canned Cycles are the most common use of subprograms. For example, you might put the X and Y locations of a series of holes in a separate program. Then you can call that program as a subprogram with a canned cycle. Instead of writing the locations once for each tool, you write the locations only once for any number of tools.

## SETTING UP SEARCH LOCATIONS

When a program calls a subprogram, the control first looks for the subprogram in the active directory. If the control cannot find the subprogram, the control uses Settings 251 and 252 to determine where to look next. Refer to those settings for more information.

To build a list of search locations in Setting 252:

In the Device Manager (LIST PROGRAM), select the directory that you want to add to the list. Press F3.

Highlight the SETTING 252 option in the menu, and then press ENTER.

The control adds the current directory to the list of search locations in Setting 252.

### Result:

To see the list of search locations, look at the values of Setting 252 on the Settings page.

## LOCAL SUBPROGRAM (M97)

A local subprogram is a block of code in the main program that is referenced several times by the main program. Local subprograms are commanded (called) using an M97 and Pnnnnn, which refers to the N line number of the local subprogram.

The local subprogram format is to end the main program with an M30 then enter the local subprograms after the M30. Each subprogram must have an N line number at the start and a M99 at the end that will send the program back to the next line in the main program.

**\*\*\* See sample Program in M97 Sample Program Folder on USB Drive; O40009.NC \*\*\***

## EXTERNAL SUBPROGRAM (M98)

An external subprogram is a separate program that the main program references. Use M98 to command (call) an external subprogram, with Pnnnnn to refer to the program number you want to call.


When your program calls an M98 subprogram, the control looks for the subprogram in the main program's directory. If the control cannot find the subprogram in the main program's directory, it then looks in the location specified in Setting 251. Refer to page5 for more information. An alarm occurs if the control cannot find the subprogram.

In this example, the subprogram (program O40008) specifies (8) positions. It also includes a G98 command at the move between positions 4 and 5. This causes the Z Axis to return to the initial starting point instead of the R plane, so the tool passes over the work holding.

## THE MAIN PROGRAM (PROGRAM O40007) SPECIFIES (3) DIFFERENT CANNED CYCLES:

- G81 Spot drill at each position
- G83 Peck drill at each position
- G84 Tap at each position

Each canned cycle calls the subprogram and does the operation at each position.



\*\*\* Main Program O40007.NC is in M98 Sample Program Folder on USB Drive \*\*\*

\*\*\* Sub Program O40008.NC is in M98 Sample Program Folder on USB Drive \*\*\*

## MACROS INTRODUCTION

**NOTE:** This control feature is optional; call your HFO for information on how to purchase it.

Macros add capabilities and flexibility to the control that are not possible with standard G-code. Some possible uses are: families of parts, custom canned cycles, complex motions, and driving optional devices. The possibilities are almost endless.

A Macro is any routine/subprogram that you can run multiple times. A macro statement can assign a value to a variable, read a value from a variable, evaluate an expression, conditionally or unconditionally branch to another point within a program, or conditionally repeat some section of a program.

Here are a few examples of the applications for Macros. The examples are outlines and not complete macro programs.

**Tools For Immediate, On-Table Fixturing** - You can semi-automate many setup procedures to assist the machinist. You can reserve tools for immediate situations that you did not anticipate in your application design. For instance, suppose a company uses a standard clamp with a standard bolt hole pattern. If you discovered, after setup, that a fixture needs an additional clamp, and suppose that you programmed macro subprogram 2000 to drill the bolt pattern of the clamp, then you only need this two-step procedure to add the clamp to the fixture:

- a) Jog the machine to the X, Y, and Z coordinates and angle where you want to place the clamp. Read the position coordinates from the machine display.
- b) Execute this command in MDI mode:

G65 P2000 Xnnn Ynnn Znnn Annn ;

Where nnn are the coordinates determined in Step a). Here, macro 2000 (P2000) does the work since it was designed to drill the clamp bolt hole pattern at the specified angle of A. Essentially, this is a custom canned cycle.

**Simple Patterns That Are Repeated**- You can define and store repeated patterns with macros. For example:

- a) Bolt hole patterns
- b) Slotting
- c) Angular patterns, any number of holes, at any angle, with any spacing
- d) Specialty milling such as soft jaws
- e) Matrix Patterns, (e.g. 12 across and 15 down)
- f) Fly-cutting a surface, (e.g. 12 inches by 5 inches using a 3 inch fly cutter)

**Automatic Offset Setting Based On The Program** - With macros, coordinate offsets can be set in each program so that setup procedures become easier and less error-prone (macro variables #2001-2800).

## MILL G-CODES

This page gives detailed descriptions of the G-codes that you use to program your Mill machine.

**CAUTION:** The sample programs in this manual have been tested for accuracy, but they are for illustrative purposes only. The programs do not define tools, offsets, or materials. They do not describe workholding or other fixturing. If you choose to run a sample program on your machine, do so in Graphics mode. Always follow safe machining practices when you run an unfamiliar program.

**NOTE:** The sample programs in this manual represent a very conservative programming style. The samples are intended to demonstrate safe and reliable programs, and they are not necessarily the fastest or most efficient way to operate a machine. The sample programs use G-codes that you might choose not to use in more efficient programs.

\*\*\* Click on **Description** in **BLUE** for more information \*\*\*

| Code | Description                                           | Group    |
|------|-------------------------------------------------------|----------|
| G00  | <a href="#">Rapid Motion Positioning</a>              | 01       |
| G01  | <a href="#">Linear Interpolation Motion</a>           | 01       |
| G02  | <a href="#">Circular Interpolation Motion CW</a>      | 01       |
| G03  | <a href="#">Circular Interpolation Motion CCW</a>     | 01       |
| G04  | <a href="#">Dwell</a>                                 | 00       |
| G09  | <a href="#">Exact Stop</a>                            | 00       |
| G10  | <a href="#">Set Offsets</a>                           | 00       |
| G12  | <a href="#">Circular Pocket Milling CW</a>            | 00       |
| G13  | <a href="#">Circular Pocket Milling CCW</a>           | 00       |
| G17  | <a href="#">XY Plane Selection</a>                    | 02       |
| G18  | <a href="#">XZ Plane Selection</a>                    | 02       |
| G19  | <a href="#">YZ Plane Selection</a>                    | 02       |
| G20  | <a href="#">Select Inches</a>                         | 06       |
| G21  | <a href="#">Select Metric</a>                         | 06       |
| G28  | <a href="#">Return To Machine Zero Point</a>          | 00       |
| G29  | <a href="#">Return From Reference Point</a>           | 00       |
| G31  | <a href="#">Feed Until Skip</a>                       | 00       |
| G35  | <a href="#">Automatic Tool Diameter Measurement</a>   | 00       |
| G36  | <a href="#">Automatic Work Offset Measurement</a>     | 00       |
| G37  | <a href="#">Automatic Tool Offset Measurement</a>     | 00       |
| G40  | <a href="#">Cutter Compensation Cancel</a>            | 07       |
| G41  | <a href="#">2D Cutter Compensation Left</a>           | 07       |
| G42  | <a href="#">2D Cutter Compensation Right</a>          | 07       |
| G43  | <a href="#">Tool Length Compensation + (Add)</a>      | 08       |
| G44  | <a href="#">Tool Length Compensation - (Subtract)</a> | 08       |
| G47  | <a href="#">Text Engraving</a>                        | 00       |
| G49  | <a href="#">G43/G44/G143 Cancel</a>                   | 08       |
| G50  | <a href="#">Cancel Scaling</a>                        | 11       |
| G51  | <a href="#">Scaling</a>                               | 11       |
| G52  | <a href="#">Set Work Coordinate System</a>            | 00 or 12 |

|             |                                                         |    |
|-------------|---------------------------------------------------------|----|
| <b>G53</b>  | <a href="#">Non-Modal Machine Coordinate Selection</a>  | 00 |
| <b>G54</b>  | <a href="#">Select Work Coordinate System #1</a>        | 12 |
| <b>G55</b>  | <a href="#">Select Work Coordinate System #2</a>        | 12 |
| <b>G56</b>  | <a href="#">Select Work Coordinate System #3</a>        | 12 |
| <b>G57</b>  | <a href="#">Select Work Coordinate System #4</a>        | 12 |
| <b>G58</b>  | <a href="#">Select Work Coordinate System #5</a>        | 12 |
| <b>G59</b>  | <a href="#">Select Work Coordinate System #6</a>        | 12 |
| <b>G60</b>  | <a href="#">Uni-Directional Positioning</a>             | 00 |
| <b>G61</b>  | <a href="#">Exact Stop Mode</a>                         | 15 |
| <b>G64</b>  | <a href="#">G61 Cancel</a>                              | 15 |
| <b>G65</b>  | <a href="#">Macro Subprogram Call Option</a>            | 00 |
| <b>G68</b>  | <a href="#">Rotation</a>                                | 16 |
| <b>G69</b>  | <a href="#">Cancel G68 Rotation</a>                     | 16 |
| <b>G70</b>  | <a href="#">Bolt Hole Circle</a>                        | 00 |
| <b>G71</b>  | <a href="#">Bolt Hole Arc</a>                           | 00 |
| <b>G72</b>  | <a href="#">Bolt Holes Along an Angle</a>               | 00 |
| <b>G73</b>  | <a href="#">High-Speed Peck Drilling Canned Cycle</a>   | 09 |
| <b>G74</b>  | <a href="#">Reverse Tap Canned Cycle</a>                | 09 |
| <b>G76</b>  | <a href="#">Fine Boring Canned Cycle</a>                | 09 |
| <b>G77</b>  | <a href="#">Back Bore Canned Cycle</a>                  | 09 |
| <b>G80</b>  | <a href="#">Canned Cycle Cancel</a>                     | 09 |
| <b>G81</b>  | <a href="#">Drill Canned Cycle</a>                      | 09 |
| <b>G82</b>  | <a href="#">Spot Drill Canned Cycle</a>                 | 09 |
| <b>G83</b>  | <a href="#">Normal Peck Drilling Canned Cycle</a>       | 09 |
| <b>G84</b>  | <a href="#">Tapping Canned Cycle</a>                    | 09 |
| <b>G85</b>  | <a href="#">Boring Canned Cycle</a>                     | 09 |
| <b>G86</b>  | <a href="#">Bore and Stop Canned Cycle</a>              | 09 |
| <b>G89</b>  | <a href="#">Bore In, Dwell, Bore Out Canned Cycle</a>   | 09 |
| <b>G90</b>  | <a href="#">Absolute Position Command</a>               | 03 |
| <b>G91</b>  | <a href="#">Incremental Position Command</a>            | 03 |
| <b>G92</b>  | <a href="#">Set Work Coordinate Systems Shift Value</a> | 00 |
| <b>G93</b>  | <a href="#">Inverse Time Feed Mode</a>                  | 05 |
| <b>G94</b>  | <a href="#">Feed Per Minute Mode</a>                    | 05 |
| <b>G95</b>  | <a href="#">Feed per Revolution</a>                     | 05 |
| <b>G98</b>  | <a href="#">Canned Cycle Initial Point Return</a>       | 10 |
| <b>G99</b>  | <a href="#">Canned Cycle R Plane Return</a>             | 10 |
| <b>G100</b> | <a href="#">Cancel Mirror Image</a>                     | 00 |
| <b>G101</b> | <a href="#">Enable Mirror Image</a>                     | 00 |
| <b>G103</b> | <a href="#">Limit Block Buffering</a>                   | 00 |
| <b>G107</b> | <a href="#">Cylindrical Mapping</a>                     | 00 |
| <b>G110</b> | <a href="#">#7 Coordinate System</a>                    | 12 |
| <b>G111</b> | <a href="#">#8 Coordinate System</a>                    | 12 |
| <b>G112</b> | <a href="#">#9 Coordinate System</a>                    | 12 |
| <b>G113</b> | <a href="#">#10 Coordinate System</a>                   | 12 |
| <b>G114</b> | <a href="#">#11 Coordinate System</a>                   | 12 |
| <b>G115</b> | <a href="#">#12 Coordinate System</a>                   | 12 |
| <b>G116</b> | <a href="#">#13 Coordinate System</a>                   | 12 |

|             |                                                                         |    |
|-------------|-------------------------------------------------------------------------|----|
| <b>G117</b> | <a href="#">#14 Coordinate System</a>                                   | 12 |
| <b>G118</b> | <a href="#">#15 Coordinate System</a>                                   | 12 |
| <b>G119</b> | <a href="#">#16 Coordinate System</a>                                   | 12 |
| <b>G120</b> | <a href="#">#17 Coordinate System</a>                                   | 12 |
| <b>G121</b> | <a href="#">#18 Coordinate System</a>                                   | 12 |
| <b>G122</b> | <a href="#">#19 Coordinate System</a>                                   | 12 |
| <b>G123</b> | <a href="#">#20 Coordinate System</a>                                   | 12 |
| <b>G124</b> | <a href="#">#21 Coordinate System</a>                                   | 12 |
| <b>G125</b> | <a href="#">#22 Coordinate System</a>                                   | 12 |
| <b>G126</b> | <a href="#">#23 Coordinate System</a>                                   | 12 |
| <b>G127</b> | <a href="#">#24 Coordinate System</a>                                   | 12 |
| <b>G128</b> | <a href="#">#25 Coordinate System</a>                                   | 12 |
| <b>G129</b> | <a href="#">#26 Coordinate System</a>                                   | 12 |
| <b>G136</b> | <a href="#">Automatic Work Offset Center Measurement</a>                | 00 |
| <b>G141</b> | <a href="#">3D+ Cutter Compensation</a>                                 | 07 |
| <b>G143</b> | <a href="#">5-Axis Tool Length Compensation +</a>                       | 08 |
| <b>G150</b> | <a href="#">General Purpose Pocket Milling</a>                          | 00 |
| <b>G154</b> | <a href="#">Select Work Coordinates P1-P99</a>                          | 12 |
| <b>G156</b> | <a href="#">Broaching Canned Cycle</a>                                  | 09 |
| <b>G167</b> | <a href="#">Modify Setting</a>                                          | 00 |
| <b>G174</b> | <a href="#">CCW Non-Vertical Rigid Tap</a>                              | 00 |
| <b>G184</b> | <a href="#">CW Non-Vertical Rigid Tap</a>                               | 00 |
| <b>G187</b> | <a href="#">Setting the Smoothness Level</a>                            | 00 |
| <b>G234</b> | <a href="#">Tool Center Point Control (TCPC)</a>                        | 08 |
| <b>G253</b> | <a href="#">G253 Orient Spindle Normal To Feature Coordinate System</a> | 00 |
| <b>G254</b> | <a href="#">Dynamic Work Offset (DWO)</a>                               | 23 |
| <b>G255</b> | <a href="#">Cancel Dynamic Work Offset (DWO)</a>                        | 23 |
| <b>G266</b> | <a href="#">Visible Axes Linear Rapid % Motion</a>                      | 00 |
| <b>G268</b> | <a href="#">Enable Feature Coordinate System</a>                        | 14 |
| <b>G269</b> | <a href="#">Disable Feature Coordinate System</a>                       | 14 |

## MILL M-CODES

This page gives detailed descriptions of the M-codes that you use to program your machine.

**CAUTION:** The sample programs in this manual have been tested for accuracy, but they are for illustrative purposes only. The programs do not define tools, offsets, or materials. They do not describe workholding or other fixturing. If you choose to run a sample program on your machine, do so in Graphics mode. Always follow safe machining practices when you run an unfamiliar program.

**NOTE:** The sample programs in this manual represent a very conservative programming style. The samples are intended to demonstrate safe and reliable programs, and they are not necessarily the fastest or most efficient way to operate a machine. The sample programs use G-codes that you might choose not to use in more efficient programs.

M-codes are miscellaneous machine commands that do not command axis motion. The format for an M-code is the letter M followed by two to three digits; for example, M03. Only one M-code is allowed per line of code. All M-codes take effect at the end of the block.

\*\*\* Click on **Description** in **BLUE** for more information \*\*\*

| M - Code  | Description                                                                        |
|-----------|------------------------------------------------------------------------------------|
| M00       | <a href="#">Stop Program</a>                                                       |
| M01       | <a href="#">Optional Program Stop</a>                                              |
| M02       | <a href="#">Program End</a>                                                        |
| M03       | <a href="#">Spindle Forward Command</a>                                            |
| M04       | <a href="#">Spindle Reverse Command</a>                                            |
| M05       | <a href="#">Spindle Stop Command</a>                                               |
| M06       | <a href="#">Tool Change</a>                                                        |
| M07       | <a href="#">Shower Coolant On</a>                                                  |
| M08 / M09 | <a href="#">Coolant On / Off</a>                                                   |
| M10 / M11 | <a href="#">Engage / Release 4th Axis Brake</a>                                    |
| M12 / M13 | <a href="#">Engage / Release 5th Axis Brake</a>                                    |
| M16       | <a href="#">Tool Change</a>                                                        |
| M19       | <a href="#">Orient Spindle</a>                                                     |
| M21-M25   | <a href="#">Optional User M Function with M-Fin</a>                                |
| M29       | <a href="#">Set Output Relay with M-Fin</a>                                        |
| M30       | <a href="#">Program End and Reset</a>                                              |
| M31       | <a href="#">Chip Conveyor Forward</a>                                              |
| M33       | <a href="#">Chip Conveyor Stop</a>                                                 |
| M34       | <a href="#">Coolant Increment</a>                                                  |
| M35       | <a href="#">Coolant Decrement</a>                                                  |
| M36       | <a href="#">Pallet Part Ready</a>                                                  |
| M39       | <a href="#">Rotate Tool Turret</a>                                                 |
| M41 / M42 | <a href="#">Low / High Gear Override</a>                                           |
| M46       | <a href="#">Qn Pmm Jump to Line</a>                                                |
| M48       | <a href="#">Validate That The Current Program is Appropriate for Loaded Pallet</a> |
| M50       | <a href="#">Pallet Change Sequence</a>                                             |

|                    |                                                      |
|--------------------|------------------------------------------------------|
| <b>M51-M55</b>     | <a href="#">Set Optional User M-codes</a>            |
| <b>M59</b>         | <a href="#">Set Output Relay</a>                     |
| <b>M61-M65</b>     | <a href="#">Clear Optional User M-codes</a>          |
| <b>M69</b>         | <a href="#">Clear Output Relay</a>                   |
| <b>M70/M71</b>     | <a href="#">Workholding Clamp / Unclamp</a>          |
| <b>M73 / M74</b>   | <a href="#">Tool Air Blast (TAB) On / Off</a>        |
| <b>M75</b>         | <a href="#">Set G35 or G136 Reference Point</a>      |
| <b>M78</b>         | <a href="#">Alarm if Skip Signal Found</a>           |
| <b>M79</b>         | <a href="#">Alarm if Skip Signal Not Found</a>       |
| <b>M80 / M81</b>   | <a href="#">Auto Door Open / Close</a>               |
| <b>M82</b>         | <a href="#">Tool Unclamp</a>                         |
| <b>M83 / M84</b>   | <a href="#">Auto Air Gun On / Off</a>                |
| <b>M86</b>         | <a href="#">Tool Clamp</a>                           |
| <b>M88 / M89</b>   | <a href="#">Through-Spindle Coolant On / Off</a>     |
| <b>M90 / M91</b>   | <a href="#">Fixture Clamp Input On / Off</a>         |
| <b>M95</b>         | <a href="#">Sleep Mode</a>                           |
| <b>M96</b>         | <a href="#">Jump If No Input</a>                     |
| <b>M97</b>         | <a href="#">Local Sub-Program Call</a>               |
| <b>M98</b>         | <a href="#">Sub-Program Call</a>                     |
| <b>M99</b>         | <a href="#">Sub-Program Return or Loop</a>           |
| <b>M104 / M105</b> | <a href="#">Probe Arm Extend/ Retract</a>            |
| <b>M109</b>        | <a href="#">Interactive User Input</a>               |
| <b>M116 / M117</b> | <a href="#">Vise Air Chips Blast On/Off</a>          |
| <b>M130 / M131</b> | <a href="#">Display Media / Cancel Display Media</a> |
| <b>M138 / M139</b> | <a href="#">Spindle Speed Variation On/Off</a>       |
| <b>M158 / M159</b> | <a href="#">Mist Condenser On/Off</a>                |
| <b>M160</b>        | <a href="#">Cancel Active PulseJet</a>               |
| <b>M161</b>        | <a href="#">PulseJet Continuous Mode</a>             |
| <b>M162</b>        | <a href="#">PulseJet Single Event Mode</a>           |
| <b>M163</b>        | <a href="#">PulseJet Modal Mode</a>                  |
| <b>M180 / M181</b> | <a href="#">Auto Window Open / Close</a>             |
| <b>M199</b>        | <a href="#">Pallet / Part Load or Program End</a>    |
| <b>M300</b>        | <a href="#">M300 - APL/Robot Custom Sequence</a>     |

## MILL SETTINGS INTRODUCTION

This page gives detailed descriptions of the settings that control the way that your machine works.

### List of Settings

Inside the **SETTINGS** tab, the settings are organized into groups. Use the **[UP]** and **[DOWN]** cursor arrow keys to highlight a setting group. Press the **[RIGHT]** cursor arrow key to see the settings in a group, . Press the **[LEFT]** cursor arrow key to return to the setting group list.

To quickly access a single setting, make sure the **SETTINGS** tab is active, type the setting number, and then press **[F1]** or, if a setting is highlighted, press the **[DOWN]** cursor.

Some settings have numerical values that fit in a given range. To change the value of these settings, type the new value and press **[ENTER]**. Other settings have specific available values that you select from a list. For these settings, use the **[RIGHT]** cursor to display the choices.

Press **[UP]** and **[DOWN]** to scroll through the options. Press **[ENTER]** to select the option.

### User Positions

This tab collects settings that control user-defined positions such as second home, tool change mid-positions, spindle center line, tailstock and travel limits.

Refer to the Settings section of this manual for more information about these position settings.

**CAUTION:** Incorrectly set user positions can cause machine crashes. Set user positions with caution, especially after you have changed your application in some way (new program, different tools, etc.). Verify and change each axis position separately.

To set a user position, jog the axis into the position you want to use, and then press F2 to set the position. If the axis position is valid, a crash warning appears (except for user travel limits). After you verify that you want to make the change to the position, the control sets the position and makes the setting active.

If the position is not valid, the message bar at the bottom of the screen gives a message to explain why the position is not valid.

To inactivate and reset user position settings, press ORIGIN while the user positions tab is active, then choose from the menu that appears.

- Press 1 to remove the value of the currently selected position setting and make it inactive.
- Press 2 to remove the values of all second home position settings and make them inactive.
- Press 3 to remove the values of all Tool Change Mid-Position settings and make them inactive.
- Press 4 to remove the values of all Max User Travel Limit settings and make them inactive.
- Press CANCEL to exit the menu without making changes.

| Setting Number | Description                                   |
|----------------|-----------------------------------------------|
| 1              | <a href="#">Auto Power Off Timer</a>          |
| 2              | <a href="#">Power Off at M30</a>              |
| 4              | <a href="#">Graphics Rapid Path</a>           |
| 5              | <a href="#">Graphics Drill Point</a>          |
| 6              | <a href="#">Front Panel Lock</a>              |
| 8              | <a href="#">Prog Memory Lock</a>              |
| 9              | <a href="#">Dimensioning</a>                  |
| 10             | <a href="#">Limit Rapid at 50%</a>            |
| 15             | <a href="#">H and T Code Agreement</a>        |
| 17             | <a href="#">Opt Stop Lock Out</a>             |
| 18             | <a href="#">Block Delete Lock Out</a>         |
| 19             | <a href="#">Feedrate Override Lock</a>        |
| 20             | <a href="#">Spindle Override Lock</a>         |
| 21             | <a href="#">Rapid Override Lock</a>           |
| 22             | <a href="#">Can Cycle Delta Z</a>             |
| 23             | <a href="#">9xxx Progs Edit Lock</a>          |
| 27             | <a href="#">G76 / G77 Shift Dir.</a>          |
| 28             | <a href="#">Can Cycle Act w/o X/Y</a>         |
| 29             | <a href="#">G91 Non-modal</a>                 |
| 31             | <a href="#">Reset Program Pointer</a>         |
| 32             | <a href="#">Coolant Override</a>              |
| 33             | <a href="#">Coordinate System</a>             |
| 34             | <a href="#">4th Axis Diameter</a>             |
| 35             | <a href="#">G60 Offset</a>                    |
| 36             | <a href="#">Program Restart</a>               |
| 39             | <a href="#">Beep @ M00, M01, M02, M30</a>     |
| 40             | <a href="#">Tool Offset Measure</a>           |
| 42             | <a href="#">M00 After Tool Change</a>         |
| 43             | <a href="#">Cutter Comp Type</a>              |
| 44             | <a href="#">Min F Radius CC%</a>              |
| 45             | <a href="#">Mirror Image X Axis</a>           |
| 46             | <a href="#">Mirror Image Y Axis</a>           |
| 47             | <a href="#">Mirror Image Z Axis</a>           |
| 48             | <a href="#">Mirror Image A Axis</a>           |
| 52             | <a href="#">G83 Retract Above R</a>           |
| 53             | <a href="#">Jog w/o Zero Return</a>           |
| 56             | <a href="#">M30 Restore Default G</a>         |
| 57             | <a href="#">Exact Stop Canned X-Y</a>         |
| 58             | <a href="#">Cutter Compensation</a>           |
| 59             | <a href="#">Probe Offset X+</a>               |
| 60             | <a href="#">Probe Offset X-</a>               |
| 61             | <a href="#">Probe Offset Y+</a>               |
| 62             | <a href="#">Probe Offset Y-</a>               |
| 63             | <a href="#">Tool Probe Width</a>              |
| 64             | <a href="#">Tool Offset Measure Uses Work</a> |
| 71             | <a href="#">Default G51 Scaling</a>           |

|     |                                               |
|-----|-----------------------------------------------|
| 72  | <a href="#">Default G68 Rotation</a>          |
| 73  | <a href="#">G68 Incremental Angle</a>         |
| 74  | <a href="#">9xxx Progs Trace</a>              |
| 75  | <a href="#">9xxx Progs Single BLK</a>         |
| 76  | <a href="#">Tool Release Lockout</a>          |
| 77  | <a href="#">Scale Integer F</a>               |
| 79  | <a href="#">5th-Axis Diameter</a>             |
| 80  | <a href="#">Mirror Image B Axis</a>           |
| 81  | <a href="#">Tool At Power Up</a>              |
| 82  | <a href="#">Language</a>                      |
| 83  | <a href="#">M30/Resets Overrides</a>          |
| 84  | <a href="#">Tool Overload Action</a>          |
| 85  | <a href="#">Maximum Corner Rounding</a>       |
| 86  | <a href="#">M39 Lockout</a>                   |
| 87  | <a href="#">Tool Change Resets Override</a>   |
| 88  | <a href="#">Reset Rests Override</a>          |
| 90  | <a href="#">Max Tools To Display</a>          |
| 101 | <a href="#">Feed Override -&gt; Rapid</a>     |
| 103 | <a href="#">Cyc Start/Fh Same Key</a>         |
| 104 | <a href="#">Jog Handle to SNGL BLK</a>        |
| 108 | <a href="#">Quick Rotary G28</a>              |
| 109 | <a href="#">Warm-Up Time in Min.</a>          |
| 110 | <a href="#">Warmup X Distance</a>             |
| 111 | <a href="#">Warmup Y Distance</a>             |
| 112 | <a href="#">Warmup Z Distance</a>             |
| 113 | <a href="#">Tool Change Method</a>            |
| 114 | <a href="#">Conveyor Cycle Time (minutes)</a> |
| 115 | <a href="#">Conveyor On-Time (minutes)</a>    |
| 117 | <a href="#">G143 Global Offset</a>            |
| 118 | <a href="#">M99 Bumps M30 Cntrs</a>           |
| 119 | <a href="#">Offset Lock</a>                   |
| 120 | <a href="#">Macro Var Lock</a>                |
| 130 | <a href="#">Tap Retract Speed</a>             |
| 131 | <a href="#">Auto Door</a>                     |
| 133 | <a href="#">Repeat Rigid Tap</a>              |
| 142 | <a href="#">Offset Chng Tolerance</a>         |
| 143 | <a href="#">Machine Data Collection Port</a>  |
| 144 | <a href="#">Feed Override -&gt; Spindle</a>   |
| 155 | <a href="#">Load Pocket Tables</a>            |
| 156 | <a href="#">Save Offsets with Program</a>     |
| 158 | <a href="#">X Screw Thermal Comp%</a>         |
| 159 | <a href="#">Y Screw Thermal Comp%</a>         |
| 160 | <a href="#">Z Screw Thermal Comp%</a>         |
| 162 | <a href="#">Default To Float</a>              |
| 163 | <a href="#">Disable .1 Jog Rate</a>           |
| 164 | <a href="#">Rotary Increment</a>              |

|     |                                                        |
|-----|--------------------------------------------------------|
| 165 | <a href="#">Ssv Variation (RPM)</a>                    |
| 166 | <a href="#">Ssv Cycle</a>                              |
| 188 | <a href="#">G51 X Scale</a>                            |
| 189 | <a href="#">G51 Y Scale</a>                            |
| 190 | <a href="#">G51 Z Scale</a>                            |
| 191 | <a href="#">Default Smoothness</a>                     |
| 196 | <a href="#">Conveyor Shutoff</a>                       |
| 197 | <a href="#">Coolant Shutoff</a>                        |
| 199 | <a href="#">Backlight Timer</a>                        |
| 216 | <a href="#">Servo and Hydraulic Shutoff</a>            |
| 238 | <a href="#">High Intensity Light Timer (minutes)</a>   |
| 239 | <a href="#">Worklight Off Timer (minutes)</a>          |
| 240 | <a href="#">Tool Life Warning</a>                      |
| 242 | <a href="#">Air Water Purge Interval</a>               |
| 243 | <a href="#">Air Water Purge On-Time</a>                |
| 245 | <a href="#">Hazardous Vibration Sensitivity</a>        |
| 247 | <a href="#">Simultaneous XYZ Motion in Tool Change</a> |
| 249 | <a href="#">Enable Haas Starup Screen</a>              |
| 250 | <a href="#">Mirror Image C Axis</a>                    |
| 251 | <a href="#">Subprogram Search Location</a>             |
| 252 | <a href="#">Custom Subprogram Search Location</a>      |
| 253 | <a href="#">Default Graphics Tool Width</a>            |
| 254 | <a href="#">5-Axis Rotary Center Distance</a>          |
| 255 | <a href="#">MRZP X Offset</a>                          |
| 256 | <a href="#">MRZP Y Offset</a>                          |
| 257 | <a href="#">MRZP Z Offset</a>                          |
| 261 | <a href="#">DPRNT Store Location</a>                   |
| 262 | <a href="#">DPRNT Destination File Path</a>            |
| 263 | <a href="#">DPRNT Port</a>                             |
| 264 | <a href="#">Autofeed Step Up</a>                       |
| 265 | <a href="#">Autofeed Step Down</a>                     |
| 266 | <a href="#">Autofeed Minimum Override</a>              |
| 267 | <a href="#">Exit Jog Mode After Idle Time</a>          |
| 268 | <a href="#">Second Home Postion X</a>                  |
| 269 | <a href="#">Second Home Position Y</a>                 |
| 270 | <a href="#">Second Home Position Z</a>                 |
| 271 | <a href="#">Second Home Position A</a>                 |
| 272 | <a href="#">Second Home Position B</a>                 |
| 273 | <a href="#">Second Home Position C</a>                 |
| 276 | <a href="#">Workholding Input Monitor</a>              |
| 277 | <a href="#">Lubrication Cycle Interval</a>             |
| 291 | <a href="#">Main Spindle Speed Limit</a>               |
| 292 | <a href="#">Door Open Spindle Speed Limit</a>          |
| 293 | <a href="#">Tool Change Mid Position X</a>             |
| 294 | <a href="#">Tool Change Mid Position Y</a>             |
| 295 | <a href="#">Tool Change Mid Position Z</a>             |
| 296 | <a href="#">Tool Change Mid Position A</a>             |

|     |                                                                 |
|-----|-----------------------------------------------------------------|
| 297 | <a href="#">Tool Change Mid Position B</a>                      |
| 298 | <a href="#">Tool Change Mid Position C</a>                      |
| 300 | <a href="#">MRZP X Offset Master</a>                            |
| 301 | <a href="#">MRZP Y Offset Master</a>                            |
| 302 | <a href="#">MRZP Z Offset Master</a>                            |
| 303 | <a href="#">MRZP X Offset Slave</a>                             |
| 304 | <a href="#">MRZP Y Offset Slave</a>                             |
| 305 | <a href="#">MRZP Z Offset Slave</a>                             |
| 306 | <a href="#">Minimum Chip Clear Time</a>                         |
| 310 | <a href="#">Min User Travel Limit A</a>                         |
| 311 | <a href="#">Min User Travel Limit B</a>                         |
| 312 | <a href="#">Min User Travel Limit C</a>                         |
| 313 | <a href="#">Max User Travel Limit X</a>                         |
| 314 | <a href="#">Max User Travel Limit Y</a>                         |
| 315 | <a href="#">Max User Travel Limit Z</a>                         |
| 316 | <a href="#">Max User Travel Limit A</a>                         |
| 317 | <a href="#">Max User Travel Limit B</a>                         |
| 318 | <a href="#">Max User Travel Limit C</a>                         |
| 323 | <a href="#">Disable Notch Filter</a>                            |
| 325 | <a href="#">Manual Mode Enabled</a>                             |
| 330 | <a href="#">MultiBoot Selection Time out</a>                    |
| 335 | <a href="#">Linear Rapid Mode</a>                               |
| 356 | <a href="#">Beeper Volume</a>                                   |
| 357 | <a href="#">Warm Up Cycle Start Idle Time</a>                   |
| 369 | <a href="#">PulseJet Injection Cycle Time</a>                   |
| 370 | <a href="#">PulseJet Single Squirt Count</a>                    |
| 372 | <a href="#">Parts Loader Type</a>                               |
| 375 | <a href="#">APL Gripper Type</a>                                |
| 376 | <a href="#">Light Curtain Enable</a>                            |
| 377 | <a href="#">Negative Work Offsets</a>                           |
| 378 | <a href="#">Safe Zone Calibrated Geometry Reference Point X</a> |
| 379 | <a href="#">Safe Zone Calibrated Geometry Reference Point Y</a> |
| 380 | <a href="#">Safe Zone Calibrated Geometry Reference Point Z</a> |
| 381 | <a href="#">Enable Touchscreen</a>                              |
| 382 | <a href="#">Disable Pallet Changer</a>                          |
| 383 | <a href="#">Table Row Size</a>                                  |
| 389 | <a href="#">Vise Unclamped Safety Check</a>                     |
| 396 | <a href="#">Enable / Disable Virtual Keyboard</a>               |
| 397 | <a href="#">Press and Hold Delay</a>                            |
| 398 | <a href="#">Header Height</a>                                   |
| 399 | <a href="#">Header Tab</a>                                      |
| 400 | <a href="#">Pallet Ready Beep Type</a>                          |
| 403 | <a href="#">Change Popup Button Size</a>                        |
| 408 | <a href="#">Exclude Tool From Safe Zone</a>                     |
| 409 | <a href="#">Default Coolant Pressure</a>                        |
| 416 | <a href="#">Media Destination</a>                               |
| 420 | <a href="#">ATC Button Behavior</a>                             |

|            |                                                            |
|------------|------------------------------------------------------------|
| <b>421</b> | <a href="#">General Orient Angle</a>                       |
| <b>422</b> | <a href="#">Lock Graphics Plane</a>                        |
| <b>423</b> | <a href="#">Help Text Icon Size</a>                        |
| <b>424</b> | <a href="#">Mist Extractor Condenser Time Out</a>          |
| <b>430</b> | <a href="#">Enable - Broken Tool Detection</a>             |
| <b>431</b> | <a href="#">Region of Interest - Broken Tool Detection</a> |
| <b>433</b> | <a href="#">Behavior - Broken Tool Detection</a>           |